

7012 RETAIN TIPS  
(as of 05/09/98 at 09:00:46 EDT )

RETAIN Technical Data

May 9, 1998

IBM Confidential

*PREFACE Preface*

This document was edited on 05/09/98 at 09:01:01 by using the BKRETAIN package.

Technical data records obtained from the IBM RETAIN database have been sorted and categorized by type. Modification to the format of the online records has been limited to relocating the abstract to the beginning of the record. The records may have been translated to lower case if the original record was in upper case.

Special thanks to Terry Judkins in Atlanta for developing the BKRETAIN package utilized in this offering.

We also want to thank Dave Schaefer for developing the code to automate this process and sharing the code with us.

## CONTENTS Table of Contents - HSF Retain Tips

TITLE	Title Page
PREFACE	Preface
CONTENTS	Table of Contents - HSF Retain Tips
1.1	Chapter 1. Engineering Change Announcements
1.1.1	ECA015 ETHERNET ADAPTER EPROMS
1.1.2	ECA060 DIAGNOSTIC DISKETTE UPDATE 2.1.1 FOR 7012
1.1.3	ECA079 UPDATE THE PUBLICATIONS ON 7012
1.1.4	ECA080 - 7012 MODEL 32H/340/350 1GB COOLING FAN
1.1.5	ECA091 X.25 ADAPTER FOR UPGRADE TO MOD 360 OR 370
1.1.6	ECA105 - POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE
1.1.7	ECA106 - POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE
1.1.8	ECA129 LED888/103 203/223 EPROM CHANGE
1.1.9	ECA 148 16 PORT CONCENTRATOR LINE PROTECTORS
1.1.10	ECA205 TURBOWAYS 100 ATM ADAPTER
1.1.11	ECA231 THUMBSCREW REPLACEMENT ON MODELS OF THE 7012 & 7030
1.1.12	ECA241 XIO PROBLEMS WHEN M/T7137 IS ATTACHED TO 7012/7030
1.1.13	ECA242 XIO PROBLEMS WHEN a 7137 IS ATTACHED TO 7012 MODELS
1.1.14	ECA243 XIO PROBLEMS WHEN 7137 IS ATTACHED TO MODELS OF 7012
1.2	Chapter 2. Service Aids and Additional Information
1.2.1	AIX 3.2.1 OR ABOVE LOADED ON SCSI DISK PRIOR TO 9333 INSTALL
1.2.2	CABLING TIPS&COLON. 64 PORT ASYNC CONTROLLER, 16 PORT CONCENTRATOR
1.2.3	CAMBEX DISK AND TAPE DRIVE DIAGNOSTICS AVAILABILITY
1.2.4	CURSOR KEYS DON'T WORK ON TTY AFTER INSTALLING AIX 3.2.3
1.2.5	ECA 148 (LINE SURGE PROTECTOR) JUMPER PLUG STICKING
1.2.6	ECA121 POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE
1.2.7	ETHERNET ADAPTER UPGRADE REQUIRED FOR AIX VER 3.2
1.2.8	ETHERNET RISER CARD JUMPER SETTING FOR 7012 MODELS 340 - 350
1.2.9	FIRMWARE FOR GXX, JXX AND RXX SMP SYSTEMS
1.2.10	G30 ELM AND MRE MEMORY
1.2.11	INVALID SIMM LOCATION FOR SRN'S 812/XXX OR 940/XXX
1.2.12	LED288 HANG ON SMP CPU WITH EXPANSION UNIT ATTACHED
1.2.13	LED8 -8 OR LED8T8
1.2.14	LED869 OR LED957 DURING IPL
1.2.15	LED888/102 700/XCX RUNNING 2.4.3 DIAGS
1.2.16	LEVEL 2 CACHE CONNECTORS MISLABELED ON CPU PLANAR
1.2.17	MACHINE TYPE 1333 (4MM TAPE DRIVE)
1.2.18	MEMORY CARDS AND SIMMS COMPATIBILITY
1.2.19	NIM INSTALL COMPATABILITY FOR 10/100 ETHERNET ADAPTER
1.2.20	ON CARD LED BLINK CODES FOR SCSI-2 ADAPTER 4-6 OR 4-7
1.2.21	PROBLEMS WITH AIX 3.2 MEMORY SCRUBBING FEATURE
1.2.22	RELOCATION KIT PART NUMBERS FOR RISC SYSTEMS
1.2.23	REMINDER&COLON. RESET DATE AND TIME AFTER DISCONNECTING BATTERY
1.2.24	SCSI-2 DIFFERENTIAL ADAPTER FAILURE ISOLATION PROCEDURE
1.2.25	SCSI-2 F/W CONTROLLERS (ALL VARIETIES) MAY CAUSE PROBLEMS
1.2.26	SMP BUMP CONSOLE FLAG
1.2.27	3153 INFO&COLON. MARKETING REFERENCE GUIDE (G520-9415)
1.2.28	5081,6091,POWERDISPLAYS 16,17 DISPLAYS
1.2.29	540MB DISK DRIVE - END OF MANUFACTURING
1.2.30	7012 AND 7030 MEMORY CARDS
1.2.31	7012 G30 MOUSE AND KEYBOARD SUPPORT
1.2.32	7012 WON'T BOOT TO DIAGNOSTICS FROM DISK
1.2.33	7012 397 & 39F FIRMWARE UPDATE FOR SYSTEM PLANAR
1.2.34	7012-G30 CPU AND MEMORY CARD REPLACEMENT PROCEDURES
1.2.35	7012-G30 DISK POWER CABLE
1.2.36	7012/3XX DOCUMENTATION ERRORS SA23-2624-XX
1.2.37	7012/39H MEMORY SIMM COMPATABILITY
1.3	Chapter 3. Parts Information Tips
1.3.1	CABLE P/N TO ATTACH 6091 TO 7010 X-STATION
1.3.2	GROUND STRAP PART NUMBER
1.3.3	5 PACK (8MM TAPES) NO LONGER AVAILABLE THROUGH PARTS SYSTEM
1.4	Chapter 4. Symptom/Fix Tips
1.4.1	CHECKSTOP ERRORS WITH S4.5 BASE MEMORY CARDS
1.4.2	D/T7012 BASE WILL NOT ATTACH TO THE SIDE MOUNTING HOLES
1.4.3	DIFFICULTY INSERTING IBM AND 3M LOGO 1/4 " TAPE CARTRIDGES.
1.4.4	FLASHING 888 DURING NETWORK BOOT ON 7012/7030 SYSTEMS
1.4.5	LED 201 HALT CAUSED BY AIX SW ON RS/6000
1.4.6	LED888/103 123/711 AFTER DISCONNECTING BATTERY
1.4.7	LOSS OF CONNECTIVITY TROUGH ETHERNET TP RISER CARD 00G1276
1.4.8	MALL, RECEIVE TIMEOUT FROM NEW RS6000 ( D/T701* )
1.4.9	SYSDMA (OR DMA_ERR) ENTRIES WITH GT3I IN 7012/7030 MACHINES
1.4.10	UNABLE TO READ/RESTORE 8MM TAPES

1.0 7012 RETAIN TIPS

Subtopics

- 1.1 Chapter 1. Engineering Change Announcements
- 1.2 Chapter 2. Service Aids and Additional Information
- 1.3 Chapter 3. Parts Information Tips
- 1.4 Chapter 4. Symptom/Fix Tips

## 1.1 Chapter 1. Engineering Change Announcements

## Subtopics

- 1.1.1 ECA015 ETHERNET ADAPTER EPROMS
- 1.1.2 ECA060 DIAGNOSTIC DISKETTE UPDATE 2.1.1 FOR 7012
- 1.1.3 ECA079 UPDATE THE PUBLICATIONS ON 7012
- 1.1.4 ECA080 - 7012 MODEL 32H/340/350 1GB COOLING FAN
- 1.1.5 ECA091 X.25 ADAPTER FOR UPGRADE TO MOD 360 OR 370
- 1.1.6 ECA105 - POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE
- 1.1.7 ECA106 - POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE
- 1.1.8 ECA129 LED888/103 203/223 EPROM CHANGE
- 1.1.9 ECA 148 16 PORT CONCENTRATOR LINE PROTECTORS
- 1.1.10 ECA205 TURBOWAYS 100 ATM ADAPTER
- 1.1.11 ECA231 THUMBSCREW REPLACEMENT ON MODELS OF THE 7012 & 7030
- 1.1.12 ECA241 XIO PROBLEMS WHEN M/T7137 IS ATTACHED TO 7012/7030
- 1.1.13 ECA242 XIO PROBLEMS WHEN a 7137 IS ATTACHED TO 7012 MODELS
- 1.1.14 ECA243 XIO PROBLEMS WHEN 7137 IS ATTACHED TO MODELS OF 7012

7012 RETAIN TIPS  
ECA015 ETHERNET ADAPTER EPROMS

1.1.1 ECA015 ETHERNET ADAPTER EPROMS

Record number: H001081

Device:	D/T701X	Service code:	33
ECA number:	ECA015	Parts source:	
EC number:	ECC73857	Publish flag:	R
Mandatory:	Y	Hit count:	UHC06365
Automatic shipment:	Y	Success count:	USC0004
Availability date:	87/12	Publication code:	PC50
Plant of control:	11	Date created:	091/11/07
Tip key:		Date last altered:	A97/11/18
		Owning B.U.:	USA

**PURPOSE:**

ECA015 PROVIDES A FIELD UPGRADE FOR ETHERNET ADAPTERS TO CORRECT THE FOLLOWING LAN COMMUNICATION PROBLEMS:

- RECEIVER HANG CONDITIONS
- IPL TCP/IP PARITY ERROR

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
701X	B/M9999999	ETHERNET EPROM KIT	B/M32G0082	00.5	01.0

**PHYSICAL CHECK:**

1. REVIEW VITAL PRODUCT DATA (VPD) TO CONFIRM THE LEVEL OF THE ETHERNET ADAPTER.
  - ETHERNET ADAPTERS AT ROS LEVELS 0008, 0009 AND 0010 REQUIRE INSTALLATION OF ECA015. THIS WILL UPGRADE THE ADAPTER TO ROS LEVEL 0028.

NOTE: IF AN ETHERNET ADAPTER IS AT ROS LEVEL 0013, 0014, 0015, 0027 OR 0028, IT DOES NOT REQUIRE ECA015.

**PREREQUISITES:**

To Install	ECA	EC	Physical Check
B/M	Required	Required	for Prerequisites

REREQUISIT S: NON

**COMPANION:** NONE

**CONCURRENT:** NONE

**DETAIL:**

ECA015 CONSISTS OF TWO MICROCODE EPROMS, A VPD MODULE, AND THE INSTRUCTIONS. ON TOP OF EACH EPROM IS AN IDENTIFICATION NUMBER WHICH CORRELATES TO A LOCATION ON THE ADAPTER. ENSURE THAT THE EPROMS ARE INSTALLED CORRECTLY WITH NOTCH FACING THE TOP EDGE OF THE ADAPTER. REFERENCE THE ECA INSTALLATION INSTRUCTIONS TO PREVENT DAMAGE WHILE INSTALLING THE EPROMS.

NOTE: ECA015 ONLY APPLIES TO FRU P/N81F7913, P/N22F9382, AND P/N71F0974. IF UNSURE, VERIFY ROS LEVEL THROUGH VITAL PRODUCT DATA.

**NOTES:** PLEASE ORDER THIS ECA THROUGH THE NORMAL ECA PROCEDURE. PROVIDE THE M/T, S/N, AND THE CUSTOMER NAME AND ADDRESS.

TIME FOR THIS ECA SHOULD BE WRITTEN TO SERVICE CODE 33, ECA015.

\*\* SERVICE CODE 33 WILL ONLY COVER THE TIME AND PARTS EXPENSE ASSOCIATED WITH THE INSTALLATION OF THE EPROMS/ECA015. IT WILL NOT REIMBURSE THE FIELD FOR ETHERNET ADAPTERS THAT ARE REPLACED IN LIEU OF ECA015.

WHEN THE ECA INSTALLATION IS COMPLETE, PERFORM THE TOPOLOGY UPDATE BY FOLLOWING THE PROCEDURES LISTED IN THE INSTALLATION INSTRUCTIONS UNDER SECTION "MACHINE RECORDS".

SPECIAL TOOL: MODULE REMOVAL TOOL P/N9900764

7012 RETAIN TIPS

ECA015 ETHERNET ADAPTER EPROMS

PARTS DISPOSITION: DISPOSE OF LOCALLY.

SAS KEYWORDS:

7012	7013	7015	7016
7012LAN	7013LAN	7015LAN	7016LAN
7012COMM	7013COMM	7015COMM	7016COMM
7012ADAPT	7013ADAPT	7015ADAPT	7016ADAPT
701XADAPT	701XLAN	701X	701XCOMM
701XEC	701XECA	7012EC	7012ECA
7013EC	7013ECA	7015EC	7015ECA
7016EC	7016ECA	RS6000	R/S6000
LED581	ECA015		

## 1.1.2 ECA060 DIAGNOSTIC DISKETTE UPDATE 2.1.1 FOR 7012

Record number: H106822

Device:	D/T7012	Service code:	33
ECA number:	ECA060	Parts source:	AUST
EC number:	ECC74357	Publish flag:	R
Mandatory:	N	Hit count:	UHC00296
Automatic shipment:	N	Success count:	USC0000
Availability date:	92/08	Publication code:	PC50
Plant of control:	26	Date created:	092/08/06
Tip key:		Date last altered:	A92/08/06
		Owning B.U.:	USA

**PURPOSE:** TO PROVIDE THE LATEST LEVEL DISKETTE DIAGNOSTICS  
VER. 2.1.1.

TO REPLACE THE PRIOR LEVEL DISKETTE DIAGNOSTICS.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
7012	B/M41F0004	7012 320 AND 32H	B/M51G8638	01.0	01.0
7012	B/M00G2561	7012 340 AND 350	B/M51G8638	01.0	01.0
7012	B/M32G1571	7012 34R AND 35R	B/M51G8638	01.0	01.0

**PHYSICAL CHECK:** NONE

**PREREQUISITES:** NONE

**COMPANION:** MAY BE INSTALLED SEPARATELY.  
MACHINE TYPE 7012: EC A90903F, PRODUCT PUBLICATIONS.

**CONCURRENT:** NONE

**DETAIL:** PROVIDE THE LATEST LEVEL DIAGNOSTICS DISKETTE PACKAGE  
2.1.1 TO SUPPORT NEW MACHINES AND DEVICES.

REPLACE DOWN LEVEL DISKETTE DIAGNOSTICS WITH THE LATEST  
RELEASED LEVEL DISKETTE DIAGNOSTICS.

PREVIOUS LEVEL OF THE DISKETTE DIAGNOSTICS MAY BE  
DISPOSED OF LOCALLY.

**NOTES:** USE SERVICE CODE 33, ECA060.

## SAS KEYWORDS:

701XECA	7012ECA	701XECA060	7012ECA060
701XECA029	7012ECA029	701XDIAG	7012DIAG
RS/6000	701XEC	7012EC	701XDISK
7012DISK	701X	7012	

## 1.1.3 ECA079 UPDATE THE PUBLICATIONS ON 7012

Record number: H084060

Device:	D/T7012	Service code:	33
ECA number:	ECA079	Parts source:	AUST
EC number:	ECC74253	Publish flag:	R
Mandatory:	N	Hit count:	UHC00168
Automatic shipment:	N	Success count:	USC0000
Availability date:	92/10	Publication code:	PC10
Plant of control:	26	Date created:	092/10/26
Tip key:		Date last altered:	A93/01/04
		Owning B.U.:	USA

**PURPOSE:**

The purpose of this ECA is to install new service and operator documentation for the M/T7012.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
7012	B/M9999999	NEW PUBLICATIONS	B/M00G1136	00.4	00.0

**PHYSICAL CHECK:** NONE**PREREQUISITES:** NONE**COMPANION:** NONE**CONCURRENT:** NONE**DETAIL:**

Release new publications in multille languages for M/T7012.

**NOTES:** NONE**SAS KEYWORDS:**

7012	7012DOC	7012PUB	7012EC
7012ECA	7012ECA079	RS6000	701XEC
701XECA	701XECA079		

## 1.1.4 ECA080 - 7012 MODEL 32H/340/350 1GB COOLING FAN

Record number: H037404

Device:	D/T7012	Service code:	33
ECA number:	ECA080	Parts source:	AUST
EC number:	ECC74287A	Publish flag:	R
Mandatory:	N	Hit count:	UHC00992
Automatic shipment:	N	Success count:	USC0002
Availability date:	92/10	Publication code:	PC30
Plant of control:	26	Date created:	092/10/28
Tip key:		Date last altered:	A94/09/21
		Owning B.U.:	USA

**PURPOSE:**

INSTALLATION OF 40MM SUPPLEMENTAL FAN TO ADEQUATELY COOL 1GB DISK DRIVE INSTALLED IN REAR POSITION OF 7012 MODELS 340, 350 AND SPECIFIC SERIAL NUMBER 32H. HARDWARE TO MOUNT THE FAN TO THE RISER CARD IS INCLUDED.

**RESTRICTIONS FOR 32H ONLY:**

BE AWARE FC 2550 AND 2555 (1GB SCSI-2 DISK DRIVE) SHOULD ONLY BE INSTALLED ON THE FOLLOWING SERIAL NUMBERS.

SER # 26-21874 OR GREATER IF BUILT IN AUSTIN, TEXAS  
 SER # 44-94964 OR GREATER IF BUILT IN SANTA PALOMBA, ITALY  
 SER # 90-M1775 OR GREATER IF BUILT IN WANGARATTA, AUSTRALIA

THE ROOM AMBIENT OPERATING TEMPERATURE MUST BE BELOW 87 DEGREES FAHRENHEIT. OPERATING THE DRIVE AT HIGHER TEMPERATURES WILL RESULT IN PREMATURE DRIVE FAILURE.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
7012	B/M43G0353	MODELS 340 AND 350	B/M51G8668	01.0	01.0

**PHYSICAL CHECK:**

CONFIRM FC 2550 OR 2555 IS INSTALLED W/O EC C74287. FAN IS MOUNTED ON SCSI RISER CARD.

**PREREQUISITES:** NONE**COMPANION:** NONE**CONCURRENT:** NONE**DETAIL:**

INSTALL SUPPLEMENTAL FAN.

**NOTES:** NONE**SAS KEYWORDS:**

7012DISK	7012MISC	7012EC	7012ECA
701XEC	701XECA	701XDISK	RS6000
RS/6000	701XMISC	701X	

## 1.1.5 ECA091 X.25 ADAPTER FOR UPGRADE TO MOD 360 OR 370

Record number: H093158

Device:	D/T7012	Service code:	33
ECA number:	ECA091	Parts source:	AUST
EC number:	ECD18448	Publish flag:	R
Mandatory:	N	Hit count:	UHC00126
Automatic shipment:	N	Success count:	USC0000
Availability date:	93/08	Publication code:	PC20
Plant of control:	26	Date created:	093/09/30
Tip key:		Date last altered:	A93/10/14
		Owning B.U.:	USA

**PURPOSE:**

ECA091 is only required when the 7012 is upgraded from a model 340 or 350 to a 7012 model 360 or 370. This package includes a set of instructions and an up level X.25 adapter card.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
7012	B/M9999999	7012 MOD 340 OR 350 WHEN UPGRADING TO A MOD 360 OR 370	B/M51G8933	01.0	00.0

**PHYSICAL CHECK:** NONE**PREREQUISITES:** NONE**COMPANION:** NONE**CONCURRENT:** NONE**DETAIL:**

Install the X.25 card as directed by the instructions included in this package. This activity includes removal of the old X.25 and installation of the new X.25 adapter.

**NOTES:**

Please account for your time and travel with S/C 33 and ECA 091

**SAS KEYWORDS:**

7012	7012CA	7012MES	7012X.25
701X	701XCA	701XMES	701XX.25
701X			

## 1.1.6 ECA105 - POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE

Record number: H121531

Device:	D/T7012	Service code:	33
ECA number:	ECA105	Parts source:	AUST
EC number:	ECD18523	Publish flag:	H
Mandatory:	N	Hit count:	UHC00523
Automatic shipment:	N	Success count:	USC0000
Availability date:	93/04	Publication code:	PC50
Plant of control:	26	Date created:	093/04/13
Tip key:		Date last altered:	A93/10/15
		Owning B.U.:	USA

**PURPOSE:**

THIS EC RELEASES A NEW LEVEL OF MICROCODE TO CORRECT A POSSIBLE DATA CORRUPTION PROBLEM WHEN AN IBM 8MM 5GB TAPE DRIVE IS USED TO LOAD AIX BASE OPERATING SYSTEM SOFTWARE CODE.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
7012	B/M9999999	ALL MODEL 340 WITH SYSTEM PLANAR ASSEMBLY P/N51G9052, P/N51G8631, OR P/N32G0163	B/M51G9546	01.3	01.3

**PHYSICAL CHECK:**

THIS EC IS INSTALLED ON THE CPU CARD IF THE ASSEMBLY PART NUMBER IS P/N51G9538 OR HIGHER, OR THE FRU PART NUMBER IS P/N51G9539 OR HIGHER.  
THE ABOVE PART NUMBERS WILL APPEAR IN VITAL PRODUCT DATA (VPD) FOR DEVICE sysplanar0 AND ON LABELS ON THE CPU CARD.

**PREREQUISITES:** NONE**COMPANION:** NONE**CONCURRENT:** NONE**DETAIL:**

FOLLOW DETAIL INSTALLATION INSTRUCTIONS PROVIDED IN THE FB/M.

**NOTES:**

NOTIFICATION ABOUT THIS POSSIBLE EXPOSURE IS ALSO RELEASED IN HONE FLASH AND IN NATBOARD CATEGORY "AIX + RS". A COPY OF THE NATBOARD NOTICE WILL BE MAILED TO ALL CUSTOMERS OF RECORD THAT HAVE PURCHASED AN IBM 8MM 5GB TAPE DRIVE.

REFER TO RETAIN TDR #H094173 FOR A COPY OF THE NATBOARD NOTICE.

RECORD MACHINE TYPE AND SERIAL NUMBER WHEN INSTALLING THIS EC.  
USE SC 33, ECA105 TO RECORD TIME AND TRAVEL ASSOCIATED WITH INSTALLATION OF THIS EC.

**SAS KEYWORDS:**

701X	7012	701XEC	7012EC
D/T701X	D/T7012	RS6000	RS/6000

## 1.1.7 ECA106 - POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE

Record number: H106232

Device:	D/T7012	Service code:	33
ECA number:	ECA106	Parts source:	AUST
EC number:	ECD18532	Publish flag:	H
Mandatory:	N	Hit count:	UHC00447
Automatic shipment:	N	Success count:	USC0000
Availability date:	93/04	Publication code:	PC50
Plant of control:	26	Date created:	093/04/13
Tip key:		Date last altered:	A93/05/06
		Owning B.U.:	USA

**PURPOSE:**

THIS EC RELEASES A NEW LEVEL OF MICROCODE TO CORRECT A POSSIBLE DATA CORRUPTION PROBLEM WHEN AN IBM 8MM 5GB TAPE DRIVE IS USED TO LOAD AIX BASE OPERATING SYSTEM SOFTWARE CODE.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
7012	B/M9999999	ALL MODEL 350 WITH SYSTEM PLANAR ASSEMBLY P/N51G9052, P/N51G8631, OR P/N32G0163	B/M52G4014	01.3	01.3

**PHYSICAL CHECK:**

THIS EC IS INSTALLED ON THE CPU CARD IF THE ASSEMBLY PART NUMBER IS P/N52G4006 OR HIGHER, OR THE FRU PART NUMBER IS P/N52G4007 OR HIGHER.  
THE ABOVE PART NUMBERS WILL APPEAR IN VITAL PRODUCT DATA (VPD) FOR DEVICE sysplanar0 AND ON LABELS ON THE CPU CARD.

**PREREQUISITES:** NONE**COMPANION:** NONE**CONCURRENT:** NONE**DETAIL:**

FOLLOW DETAIL INSTALLATION INSTRUCTIONS PROVIDED IN THE FB/M.

**NOTES:**

NOTIFICATION ABOUT THIS POSSIBLE EXPOSURE IS ALSO RELEASED IN HONE FLASH AND IN NATBOARD CATEGORY "AIX + RS". A COPY OF THE NATBOARD NOTICE WILL BE MAILED TO ALL CUSTOMERS OF RECORD THAT HAVE PURCHASED AN IBM 8MM 5GB TAPE DRIVE.

REFER TO RETAIN TDR #H094173 FOR A COPY OF THE NATBOARD NOTICE.

RECORD MACHINE TYPE AND SERIAL NUMBER WHEN INSTALLING THIS EC. USE SC 33, ECA106 TO RECORD TIME AND EXPENSES ASSOCIATED WITH INSTALLATION OF THIS EC.

**SAS KEYWORDS:**

701X	7012	701XEC	7012EC
D/T701X	D/T7012	RS6000	RS/6000

## 1.1.8 ECA129 LED888/103 203/223 EPROM CHANGE

Record number: H007199

Device:	D/T7012	Service code:	33
ECA number:	ECA129	Parts source:	AUST
EC number:	ECD18569	Publish flag:	R
Mandatory:	N	Hit count:	UHC00383
Automatic shipment:	N	Success count:	USC0000
Availability date:	93/09	Publication code:	PC30
Plant of control:	26	Date created:	093/09/13
Tip key:		Date last altered:	A97/04/21
		Owning B.U.:	USA

**PURPOSE:**

Replace the IPL ROS and VPD Eproms on the 7012 model 340 for LED888/103/203/223 with color graphic display adapter 1-1 installed.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
7012	B/M9999999	D/T7012 MODEL340 WITH COLOR GRAPHICS ADAPTER INSTALLED	B/M52G4311	00.5	00.0

**PHYSICAL CHECK:**

Please verify that the D/T7012 model 340 has a color graphics adapter type installed, and the CPU planar FRU part number P/N32G0060 EC C73978 or lower.

**PREREQUISITES:**

The prereqs are a D/T7012 model 340 with a color graphics adapter type 1-1 installed failing with LED888/103 203/223.

**COMPANION:** NONE**CONCURRENT:** NONE**DETAIL:**

This ECA releases two EPROM's and a set of instructions. Installation of these EPROM's is only required if the D/T7012 model 340 is failing with LED888/103 203/223. And the system has a color graphics adapter type 1-1 installed in CPU card level P/N00G3149 EC C73978 and below. The P/N and EC level of the CPU card can be determined by running concurrent diagnostics on the system. This activity includes being signed on as the super user or in the root directory. Next type 'diag' at the command line. At the next screen press enter. At the Function Selection screen select 'Service Aid' and press enter. At the Service Aids Selection Screen select 'Display or Change Configuration or Vital Product Data' and press enter. At the Display or Change Configuration or Vital Product Data ... screen select 'Display Vital Product Data' then press enter. At the Installed Resource List with VPD find the listing for the CPU card and review the CPU card P/N and EC level.

**NOTES:**

Please account for your time with S/C 33 and ECA 129.

**SAS KEYWORDS:**

7012	701X	7012CA	701XCA
7012ECA	7012ECA	701XEPROM	7012EPROM
7012VPD	701XVPD	7012CPU	701XCPU
7012LED	701XLED	7012888	701X888
SRN	SRN203/223		

## ECA 148 16 PORT CONCENTRATOR LINE PROTECTORS

## 1.1.9 ECA 148 16 PORT CONCENTRATOR LINE PROTECTORS

Record number: H123714

Device:	D/T7013	Service code:	33
ECA number:	ECA148	Parts source:	AUST
EC number:	ECD18314	Publish flag:	R
Mandatory:	N	Hit count:	UHC01544
Automatic shipment:	N	Success count:	USC0002
Availability date:	94/05	Publication code:	PC30
Plant of control:	26	Date created:	094/04/26
Tip key:		Date last altered:	A98/02/23
		Owning B.U.:	USA

**PURPOSE:**

Protect 16 port concentrators from lightning or ESD damage.  
Kit includes: two lightning protection devices (each protects 8 ports) and short cables (16) and instructions.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
701X	B/M9999999	ALL 701X WITH F/C 6401 W/O LIGHTNING PROTECTORS INSTALLED.	B/M8184324	01.0	00.0

**PHYSICAL CHECK:** NONE**PREREQUISITES:** NONE**COMPANION:** NONE**CONCURRENT:** NONE**DETAIL:**

These 16 port lightning/ESD protector kits should be ordered for 64 port customers with the following conditions:  
Concentrators that have been BLOWN DURING THUNDERSTORMS.  
(Replace currently bad concentrators and order this ECA for concentrators on the system)  
Concentrator port hangs that CANNOT BE RESET.  
(Replace currently bad concentrators if any, install LP kits on all concentrators on the system)  
Concentrator port hangs that CAN BE RESET.  
(Not necessary to replace concentrator, install LP kit which should prevent further occurrences unless bad cable conditions exist)  
Customers located in storm hazardous area with medium to long (100 - 200ft) cabling distances to terminal devices.  
Customers located in highly industrial areas with long (150-200ft) cabling distances to terminal devices.  
THESE KITS SHOULD NEVER BE USED IN PLACE OF OUTDOOR SURGE PROTECTORS WHEN GOING OUT OF DOORS OR BETWEEN BUILDINGS.

**NOTES:**

Please account for time and travel with S/C 33 and ECA 148.

**SAS KEYWORDS:**

701XECA	7011	701X	7012
7013	7015	RS/6000	16 PORT ECA
7013ECA	7011ECA	7012ECA	7013ECA
7015ECA	7011COMM	7012COMM	7013COMM
7015COMM	ECA148	ECA	148

**7012 RETAIN TIPS**  
**ECA205 TURBOWAYS 100 ATM ADAPTER**

1.1.10 ECA205 TURBOWAYS 100 ATM ADAPTER

Record number: H13692

Device:	D/T7012	Service code:	33
ECA number:	ECA205	Parts source:	AUS
EC number:	ECD28493	Publish flag:	R
Mandatory:	Y	Hit count:	UHC00277
Automatic shipment:	N	Success count:	USC0000
Availability date:	09/01	Publication code:	PC40
Plant of control:	26	Date created:	095/08/31
Tip key:		Date last altered:	A95/09/13
		Owning B.U.:	USA

**PURPOSE:** IBM HAS IDENTIFIED A POSSIBLE EXPOSURE TO DATA INTEGRITY WITH THE TURBOWAYS 100 ATM MICROCHANNEL ADAPTER (FC 2984) UNDER VERY HEAVY NETWORK LOADS. ALTHOUGH IT IS HIGHLY UNLIKELY THAT THIS PROBLEM WILL OCCUR, IBM WISHES TO REPLACE ALL INSTALLED ADAPTERS. THIS EXPOSURE IS FURTHER MINIMIZED UNDER AIX AND TCP/IP WHEN THE UDP CHECKSUM IS SET TO ON.

ECA 205 IS PROVIDED TO REPLACE INSTALLED ADAPTERS WITH THE NEW LEVEL. THE ECA CONTAINS A REPLACEMENT ADAPTER, INSTALLATION INSTRUCTIONS AND A PRE-PAID MAILING LABEL FOR RETURNING THE THE OLD ADAPTER TO THE FACTORY FOR REWORK.

ECA205 SHOULD BE ORDERED VIA NORMAL CHANNELS.

**FEATURES:**

Type, Model, Stage	With B/M	Machines Affected and/or Feature/Device Description	B/M to be Installed	Service Hours	System Hours
701X	B/M9999999	7006, 7009, 7012, 7013 7015, 7030	B/M40H3292	01.5	01.0

**PHYSICAL CHECK:** THE WAY TO IDENTIFY A DOWN LEVEL ADAPTER IS BY PHYSICALLY CHECKING FOR ASSEMBLY P/N 10H4472, OR 73G6466. THE NEW LEVEL WILL BE ASSEMBLY P/N10H4538, 10H4542, 10H4539 OR 13H5987.

THE FOLLOWING IS A LIST OF MACHINES THAT CONTAIN THIS FEATURE AND SHOULD BE INSPECTED TO ENSURE THE PROPER LEVEL ADAPTER.

MACHINE			MACHINE		
TYPE	MOD	SERIAL	TYPE	MOD	SERIAL
7006	41T	260000954	7013	520	260001755
7006	41T	260000968	7013	520	260001989
7006	41T	260000969	7013	520	260011031
7006	41T	260000970	7013	56F	260014381
7006	41T	260001155	7013	530	260015999
7006	41T	260004822	7013	56F	260023710
7006	41T	260005079	7013	560	260024770
7006	41T	260005080	7013	560	260027410
7006	41T	260005592	7013	550	260027885
7006	41T	260005593	7013	550	260027886
7006	41T	260005594	7013	560	260029603
7006	41T	260005595	7013	52H	260030120
7006	41T	260005596	7013	560	260030326
7006	41T	260005753	7013	53H	260031329
			7013	580	260034811
7009	C10	260003371	7013	580	260035678
7009	C10	260003372	7013	580	260037750
7009	C10	260004216	7013	580	260038350
7009	C10	260004275	7013	580	260038351
7009	C10	260006887	7013	55L	260038579
7009	C10	260007742	7013	55L	260038580
7009	C10	260008000	7013	580	260039415
			7013	590	260039485
			7013	590	260039512
			7013	590	260039513
7012	320	260024153	7013	590	260040844
7012	350	260036169	7013	570	260041872
7012	340	260036455	7013	590	260042375
7012	340	260037069	7013	590	260042450
7012	340	260037070	7013	590	260042488
7012	340	260037071	7013	59H	260042547
7012	340	260037072	7013	590	260043039
7012	340	260039748	7013	590	260043347
7012	340	260043019	7013	590	260043519
7012	340	260043341	7013	590	260043654
7012	340	260044694	7013	590	260043683
7012	340	260050384	7013	590	260043806
7012	370	260053278	7013	59H	260043923
7012	350	260053592	7013	59H	260044010

**7012 RETAIN TIPS**  
**ECA205 TURBOWAYS 100 ATM ADAPTER**

7012	350	260054631	7013	58H	260044112
7012	350	260054657	7013	590	260044321
7012	340	260056989	7013	590	260044472
7012	370	260057160	7013	590	260044479
7012	370	260058468	7013	590	260044480
7012	370	260059064	7013	570	260044843
7012	340	260060116	7013	570	260044844
7012	370	260060926	7013	570	260044845
7012	370	260060928	7013	570	260044872
7012	370	260060947	7013	590	260044948
7012	360	260061171	7013	570	260044985
7012	360	260062915	7013	590	260045017
7012	37T	260069087	7013	590	260045174
7012	370	260069900	7013	590	260045175
7012	370	260069917	7013	590	260045176
7012	370	260069928	7013	590	260045177
7012	370	260069957	7013	59H	260045411
7012	370	260069966	7013	590	260045669
7012	37T	260072918	7013	59H	260045727
7012	37T	260073098	7013	590	260045758
7012	37T	260074826	7013	59H	260045849
7012	37T	260074827	7013	570	260046032
7012	360	260075762	7013	570	260046301
7012	360	260076292	7013	570	260046785
7012	360	260076293	7013	59H	260046996
7012	360	260076294	7013	570	260047082
7012	390	260076309	7013	570	260047250
7012	390	260076310	7013	570	260047648
7012	370	260076397	7013	570	260047740
7012	390	260076414	7013	590	260048018
7012	390	260076415	7013	590	260048019
7012	390	260076416	7013	590	260048020
7012	390	260076417	7013	590	260048021
7012	390	260076584	7013	590	260048022
7012	370	260076737			
7012	380	260076967	7015	99F	260002142
7012	370	260077529	7015	99F	260002142
7012	390	260078875	7015	97B	260004332
7012	390	260079192	7015	97B	260004539
7012	390	260079193	7015	990	260004736
7012	370	260080166	7015	990	260004736
7012	390	260080475	7015	990	260004753
7012	39H	260081538	7015	R20	260006044
7012	390	260081556	7015	R30	260006379
7012	390	260081651	7015	R30	260006380
7012	39H	260081766	7015	R24	260006424
7012	39H	260081767	7015	R24	260006428
7012	380	260081801	7015	R24	260006714
7012	380	260081802	7015	R24	260006825
7012	360	260081842	7015	R24	260007149
7012	360	260081843	7015	R24	260007202
7012	360	260081844	7015	R24	260007452
			7015	R24	260007466
			7015	R24	260007468
			7015	R24	260007556
7030	3AT	2600AAAYT			
7030	3AT	2600AABLQ			
7030	3BT	2600AABNR			
7030	3BT	2600AACHK			
7030	3BT	2600AACHL			
7030	3BT	2600AACHM			
7030	3BT	2600AACHN			
7030	3AT	2600AAKWL			

**PREREQUISITES:** NONE

**COMPANION:** NONE

**CONCURRENT:** NONE

**DETAIL:** NONE

**NOTES:** ALL LABOR SHOULD BE RECORDED USING SC 33 AGAINST ECA 205.

**SAS KEYWORDS:**

ECA205	701XECA	TURBOWAYS	701XATM
701XECA205	7006	7009	7012
7013	7015	7006ECA	7009ECA
7012ECA	7015ECA	7030	7030ECA
7006ECA205	7009ECA205	7012ECA205	7013ECA205
7015ECA205	7030ECA205	RS6000	ATM
701X			

7012 RETAIN TIPS

ECA231 THUMBSCREW REPLACEMENT ON MODELS OF THE 7012 7030

1.1.11 ECA231 THUMBSCREW REPLACEMENT ON MODELS OF THE 7012 & 7030

Record number: H133538

Device:	D/T7012	Date created:	096/07/10
Model:	M	Date last altered:	A96/07/10
EC number:	ECE75819	Owning B.U.:	USA
ECA number:	ECA231		
Index B/M:	B/M93H1620		
Tip key:	016		

BILL OF MATERIALS:  
B/M93H1620

THIS ECA AFFECTS MACHINE TYPE 7012 MOD. 380, 390, 39H AND MACHINE TYPE 7030 MOD. 3AT, 3BT AND 3CT ONLY.

THE INTENT OF THIS ECA IS TO PROVIDE A B/M THAT WILL ENABLE THE REPLACEMENT OF THE FRAME THUMBSCREW ASSLY EXPERIENCING BREAKAGE DUE TO OVER TORQUE OF THE KNURLED RETAINER.

ALL TIME ASSOCIATED WITH THIS ECA SHOULD BE WRITTEN OFF TO SC 33

SAS KEYWORDS:

7012	7030	ECA231	THUMBSCREW
380ECA	390ECA	39HECA	3ATECA
3BTECA	3CTECA	7012ECA	7030ECA
7012ECA231	7030ECA231	701XECA	

## 1.1.12 ECA241 XIO PROBLEMS WHEN M/T7137 IS ATTACHED TO 7012/7030

Record number: H134233

Device:	D/T7012	Date created:	O96/10/01
Model:	M	Date last altered:	A96/12/13
EC number:	ECE76229	Owning B.U.:	USA
ECA number:	ECA241		
Index B/M:	B/M93H3703		
Tip key:	017		

BILL OF MATERIALS:  
B/M93H3703

This is an as required FB/M for the following models that could experience XIO problems and do not have an I/O Planar at EC level E76229 or higher. 7012-380,390,39H, 7030-3AT, 3BT and 3CT. This EC is required to ensure proper operation of M/T7137 when attached via SCSI to one of the RS/6000 mentioned above.

**PHYSICAL CHECK:** If M/T7137 is connected to the RS/6000 and the I/O Planar is not at EC level E76229 or higher. The EC level can be determined electronically by interrogating VPD. (M/T7137 with serial numbers 6000 and higher).

**DETAIL:** The installation instructions will refer the CSR/CE to the Service Manual for planar removal.

- U.S. CSR/CEs should order this ECA via the normal ECA ordering process for their geography.
- Customers should be advised not to reconfigure the RS/6000 and attach a 7137 unless they notify IBM service.

## SAS KEYWORDS:

7012	ECA241	7012ECA	7012ECA241
RISC	RISCECA	7012380	7012390
701239H	70303AT	70303BT	70303CT
7030	D/T7137	M/T7137	7137
RS6000	3BT	3AT	380
390			

## 1.1.13 ECA242 XIO PROBLEMS WHEN a 7137 IS ATTACHED TO 7012 MODELS

Record number: H135016

Device:	D/T7012	Date created:	096/10/28
Model:	M	Date last altered:	A96/10/28
EC number:	ECE76276A	Owning B.U.:	USA
ECA number:	ECA242		
Index B/M:	B/M93H4293		
Tip key:	018		

BILL OF MATERIALS:  
B/M93H4293

This is an as required FB/M for the following models that could experience XIO problems and do not have an I/O Planar at EC level E76276 or higher. 7012-315, 355, 365 and 375.

This EC is required to ensure proper operation of M/T 7137 when attached via SCSI to one of the RS/6000 mentioned above.

**PHYSICAL CHECK:** If M/T 7137 is connected to the RS/6000 and the I/O Planar is not at EC level E76276 or higher. The EC level can be determined electronically by interrogating VPD.

**DETAIL:** The installation instructions will refer the CSR/CE to the Service Manual for planar removal.

- U.S. CSR/CEs should order this ECA via the normal ECA ordering process for their geography.
- Customers should be advised not to reconfigure the RS/6000 and attach a 7137 unless they notify IBM service.

## SAS KEYWORDS:

ECA242	7012	7012ECA	7012ECA242
315	355	365	375
315ECA	355ECA	365ECA	375ECA
RISC	RISCECA	RISCECA242	D/T7012
D/T7137	7137	XIO	701X
701XECA			

## 1.1.14 ECA243 XIO PROBLEMS WHEN 7137 IS ATTACHED TO MODELS OF 7012

Record number: H135017

Device:	D/T7012	Date created:	096/10/28
Model:	M	Date last altered:	A96/10/28
EC number:	ECE76276A	Owning B.U.:	USA
ECA number:	ECA243		
Index B/M:	B/M93H4309		
Tip key:	019		

BILL OF MATERIALS:  
B/M93H4309

This is an as required FB/M for the following models that could experience XIO problems and do not have an I/O Planar at EC level E76320 or higher. 7012-360, 370, 34H, 35T and 7013-55L.

This EC is required to ensure proper operation of M/T 7137 when attached via SCSI to one of the RS/6000 mentioned above.

**PHYSICAL CHECK:** If M/T 7137 is connected to the RS/6000 and the I/O Planar is not at EC level E76320 or higher. The EC level can be determined electronically by interrogating VPD.

**DETAIL:** The installation instructions will refer the CSR/CE to the Service Manual for planar removal.

- U.S. CSR/CEs should order this ECA via the normal ECA ordering process for their geography.
- Customers should be advised not to reconfigure the RS/6000 and attach a 7137 unless they notify IBM service.

## SAS KEYWORDS:

ECA243	7012	7012ECA	7012ECA243
360	370	34H	35T
360ECA	370ECA	34HECA	35TECA
RISC	RISCECA	RISCECA243	D/T7012
D/T7137	7137	XIO	701X
701XECA	7013	7013ECA	7013ECA243
55L	55LECA	55LECA243	

## 1.2 Chapter 2. Service Aids and Additional Information

## Subtopics

- 1.2.1 AIX 3.2.1 OR ABOVE LOADED ON SCSI DISK PRIOR TO 9333 INSTALL
- 1.2.2 CABLING TIPS&COLON. 64 PORT ASYNC CONTROLLER, 16 PORT CONCENTRATOR
- 1.2.3 CAMEX DISK AND TAPE DRIVE DIAGNOSTICS AVAILABILITY
- 1.2.4 CURSOR KEYS DON'T WORK ON TTY AFTER INSTALLING AIX 3.2.3
- 1.2.5 ECA 148 (LINE SURGE PROTECTOR) JUMPER PLUG STICKING
- 1.2.6 ECA121 POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE
- 1.2.7 ETHERNET ADAPTER UPGRADE REQUIRED FOR AIX VER 3.2
- 1.2.8 ETHERNET RISER CARD JUMPER SETTING FOR 7012 MODELS 340 - 350
- 1.2.9 FIRMWARE FOR GXX, JXX AND RXX SMP SYSTEMS
- 1.2.10 G30 ELM AND MRE MEMORY
- 1.2.11 INVALID SIMM LOCATION FOR SRN'S 812/XXX OR 940/XXX
- 1.2.12 LED288 HANG ON SMP CPU WITH EXPANSION UNIT ATTACHED
- 1.2.13 LED8|-8 OR LED8T8
- 1.2.14 LED869 OR LED957 DURING IPL
- 1.2.15 LED888/102 700/XCX RUNNING 2.4.3 DIAGS
- 1.2.16 LEVEL 2 CACHE CONNECTORS MISLABELED ON CPU PLANAR
- 1.2.17 MACHINE TYPE 1333 (4MM TAPE DRIVE)
- 1.2.18 MEMORY CARDS AND SIMMS COMPATIBILITY
- 1.2.19 NIM INSTALL COMPATABILITY FOR 10/100 ETHERNET ADAPTER
- 1.2.20 ON CARD LED BLINK CODES FOR SCSI-2 ADAPTER 4-6 OR 4-7
- 1.2.21 PROBLEMS WITH AIX 3.2 MEMORY SCRUBBING FEATURE
- 1.2.22 RELOCATION KIT PART NUMBERS FOR RISC SYSTEMS
- 1.2.23 REMINDER&COLON. RESET DATE AND TIME AFTER DISCONNECTING BATTERY
- 1.2.24 SCSI-2 DIFFERENTIAL ADAPTER FAILURE ISOLATION PROCEDURE
- 1.2.25 SCSI-2 F/W CONTROLLERS (ALL VARIETIES) MAY CAUSE PROBLEMS
- 1.2.26 SMP BUMP CONSOLE FLAG
- 1.2.27 3153 INFO&COLON. MARKETING REFERENCE GUIDE (G520-9415)
- 1.2.28 5081,6091,POWERDISPLAYS 16,17 DISPLAYS
- 1.2.29 540MB DISK DRIVE - END OF MANUFACTURING
- 1.2.30 7012 AND 7030 MEMORY CARDS
- 1.2.31 7012 G30 MOUSE AND KEYBOARD SUPPORT
- 1.2.32 7012 WON'T BOOT TO DIAGNOSTICS FROM DISK
- 1.2.33 7012 397 & 39F FIRMWARE UPDATE FOR SYSTEM PLANAR
- 1.2.34 7012-G30 CPU AND MEMORY CARD REPLACEMENT PROCEDURES
- 1.2.35 7012-G30 DISK POWER CABLE
- 1.2.36 7012/3XX DOCUMENTATION ERRORS SA23-2624-XX
- 1.2.37 7012/39H MEMORY SIMM COMPATABILITY

## 1.2.1 AIX 3.2.1 OR ABOVE LOADED ON SCSI DISK PRIOR TO 9333 INSTALL

Record number: H097801

Device: D/T701X  
Model: M  
Tip key: 118  
Date created: 092/05/29  
Date last altered: A92/06/29

PRIOR TO INSTALLATION OF A 9333 MODEL 010 OR MODEL 500, AIX 3.2.1 OR ABOVE MUST BE INSTALLED ON A SCSI ATTACHED DISK DRIVE. THE CURRENT RELEASE OF AIX DOES NOT PROVIDE THE ABILITY TO LOAD SOFTWARE TO A SERIAL ATTACHED 9333.

A FUTURE SOFTWARE RELEASE WILL ALLOW THE STANDALONE INSTALLATION OF 9333'S.

## SAS KEYWORDS:

RS6000	RS/6000	RISC	RISC6000
D/T7011	D/T7012	D/T7013	D/T7015
D/T7016	D/T7018	D/T9333	9333
7011	7012	7013	7015
7016	7018	7011	

## 1.2.2 CABLING TIPS&amp;COLON. 64 PORT ASYNC CONTROLLER, 16 PORT CONCENTRATOR

Record number: H087916

Device: D/T701X  
 Model: M  
 Tip key: 065  
 Date created: 091/05/28  
 Date last altered: A91/11/21

THIS TDR LISTS CERTAIN GUIDELINES AND PRACTICES FOR THE CABLES USED ON THE 16 PORT CONCENTRATOR ATTACHED TO THE 64 PORT ASYNC CONTROLLER IN THE RISC SYSTEM/6000.

\*WARNING\* THE RECEIVERS AND DRIVERS USED IN THE 16 PORT CONCENTRATOR ARE EXTREMELY SENSITIVE TO ESD (ELECTRO-STATIC DISCHARGES). THE ESD EXPOSURE CAN BE SIGNIFICANTLY REDUCED BY OBSERVING THE FOLLOWING CABLING PRACTICES ON DEVICE CABLES ATTACHED TO THE 16 PORT CONCENTRATOR (CLUSTER) BOXES.

1. DO NOT LEAVE ANY CONDUCTORS/LEADS/PINS EXPOSED WHERE THEY CAN BE TOUCHED BY A PERSON WHO IS NOT PROTECTED AGAINST ELECTRO-STATIC DISCHARGE (ESD). AVOID THE USE OF TYPE 66 PUNCHDOWN BLOCKS OR SIMILAR TERMINAL BLOCKS.
2. DO NOT TOUCH ANY EXPOSED CONNECTOR PINS, WIRE LEADS OR ANY CONDUCTOR OF CABLES WITHOUT BEING THOROUGHLY GROUNDED.
3. DO NOT RUN ANY CABLES OUTDOORS WITHOUT PROPER TRANSIENT VOLTAGE SUPPRESSION DEVICES INSTALLED.
4. CARE MUST BE TAKEN WHEN CABLES ARE ROUTED NEAR OR AROUND POWER TRANSFORMERS, OR HIGH POWER SWITCHING DEVICES, REFRIGERATION UNITS, ..ETC.
5. USE SHIELDED CABLES. ALL WIRES SHOULD BE TERMINATED, NOT FLOATING. THE SHIELD SHOULD BE CONNECTED TO SHIELD GROUND AT THE CONCENTRATOR OR DEVICE, NOT BOTH.
6. DO NOT TIE FRAME (SHIELD) GROUND AND SIGNAL GROUND TOGETHER IN THE CABLE OR AT THE CONCENTRATOR.

## MACHINES AFFECTED:

D/T7012, D/T7013, D/T7015, D/T7016, D/T7018.

## SAS KEYWORDS:

701X	701XCABLE	701XMISC	701X64PORT
7012	7012CABLE	7012MISC	701264PORT
7013	7013CABLE	7013MISC	701364PORT
7015	7015CABLE	7015MISC	701564PORT
7016	7016CABLE	7016MISC	701664PORT
7018	7018CABLE	7018MISC	701864PORT
RS6000	RS/6000	HOT	BOX
701XDISP			

## 1.2.3 CAMBEX DISK AND TAPE DRIVE DIAGNOSTICS AVAILABILITY

Record number: H121562

Device: D/T1535  
Model: M  
Tip key: 002  
Date created: 093/05/03  
Date last altered: A93/08/31

Cambex Corporation ships diagnostics to distributors who re-sell their tape and disk drives. If these diagnostics are not present at the customer's machine, they may be acquired by calling Cambex Corporation Technical Support at 1-800-325-5594 between the hours of 8: 30AM and 5: 30PM EST.

These diagnostics come as installp images on diskette.

## SAS KEYWORDS:

D/T1535	D/T7011	D/T7012	D/T7013
D/T7015	1535	7011	7012
7013	7015	POEM	701X

## 1.2.4 CURSOR KEYS DON'T WORK ON TTY AFTER INSTALLING AIX 3.2.3

Record number: H015309

Device: D/T701X  
 Model: M  
 Tip key: 136  
 Date created: 092/10/28  
 Date last altered: A93/02/04

MACHINES AFFECTED: D/T7011, D/T7012, D/T7013, D/T7015

A PROBLEM HAS BEEN IDENTIFIED THAT CAUSES THE CURSOR MOVEMENT KEYS TO BE NON-FUNCTIONAL ON ATTACHED ASCII TERMINALS (TTY) AFTER INSTALLING AIX VERSION 3.2.3.

AS A TEMPORARY WORKAROUND <CNTL>N MAY BE USED TO MOVE THE CURSOR DOWN AND <CNTL>P TO MOVE THE CURSOR UP WHEN SELECTING ITEMS IN A LIST.

THIS PROBLEM WILL ALSO CAUSE GARBAGE TO BE DISPLAYED ON THE TTY IDENTIFIED AS THE SYSTEM CONSOLE DURING IPL. ANY MESSAGES DISPLAYED PRIOR TO THE LOGIN PROMPT WILL BE UNREADABLE.

PTF U412816 IS AVAILABLE FROM AIX SW DEFECT SUPPORT TO FIX THIS PROBLEM.

## SAS KEYWORDS:

701X	7011	7012	7013
7015	701XDISP	7011DISP	7012DISP
7013DISP	7015DISP	701XMISC	7011MISC
7012MISC	7013MISC	7015MISC	RS/6000
RS6000	3151	AIX	

## ECA 148 (LINE SURGE PROTECTOR) JUMPER PLUG STICKING

## 1.2.5 ECA 148 (LINE SURGE PROTECTOR) JUMPER PLUG STICKING

Record number: H125200

Device: D/T701X  
 Model: M  
 Tip key: 193  
 Date created: 094/09/12  
 Date last altered: A94/09/14

PROBLEM: SOME LINE PROTECTORS HAVE TIGHT SOCKETS THAT MAKE REMOVING THE JUMPER PLUGS VERY DIFFICULT.

**FIX:** LOCATE THE TIGHT JUMPERS, GRIP THE CONNECTOR HOUSING AND SQUEEZE THE LOCK TAB (ON THE BOTTOM), PUSH THE CONNECTOR DEEPER INTO THE SOCKET. THEN WHILE COCKING THE WHOLE CONNECTOR SLIGHTLY UP, FORCEFULLY PULL UP AND OUT.

THE CONNECTOR MAY NEED TO BE ROCKED UP AND DOWN A BIT TO LOOSEN, HOWEVER SUCCESSIVE REMOVALS SHOULD LESSEN THE TIGHTNESS.

## SAS KEYWORDS:

D/T701X	D/T7011	D/T7012	D/T7013
D/T7015	D/T7016	D/T7018	7011
7012	7013	7015	7016
7018	64PORT	ECA148	

## ECA121 POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE

## 1.2.6 ECA121 POSSIBLE DATA CORRUPTION WITH 8MM 5GB TAPE DRIVE

Record number: H133018

Device: D/T7208  
 Model: M  
 Tip key: 011  
 Date created: 096/03/11  
 Date last altered: A96/03/11

THIS EC RELEASES A NEW LEVEL OF MICROCODE TO CORRECT A POSSIBLE DATA CORRUPTION PROBLEM WHEN AN IBM 8MM 5GB TAPE DRIVE IS USED TO LOAD AIX BASE OPERATING SYSTEM SOFTWARE CODE.

If the SCSI microchannel adapter card is p/n 71f0913 or p/n 00G2362 or p/n 00G1887, then this ECA121 should be applied.

NOTE: THIS ECA WAS ORIGINALLY RELEASED AS ECA104 BUT THEN RE-RELEASED AS ECA121 BUT WAS INADVERTENTLY REMOVED FROM RETAIN

Notification about the possible exposure problem was released via HONE Flash and in NATBOARD in 05/93. A copy of the notice was also mailed to all customers of record whom had purchased a tape drive a that time.

Since this time, newer hardware and uplevel software had resolved most field exposures but, there may be customers who are still using "older" hardware level and this eca121 may be needed.

ECA121 can be ordered via the Chicago Advanced Workstation Support Center through TEMPEC.  
 Please see eca105-eca108 for similar information.

Use Service Code=33, Service Hours=01.3, System Hours=01.3 to record time and expenses associated with installation of this eca.

## SAS KEYWORDS:

701X	7208	5GB	TAPE DRIVE
RS/6000	RS6000	RISC SYSTEM	AIX
ECA121	ECA 121	7006	7009
7011	7012	7013	7015
7020	7248	7024	SCSI
MICROCHANNEL	ADAPTER	DATA INTEGRITY	CORRUPTION
MICROCODE	UCODE	D/T7011	D/T7012
D/T7013	D/T7015	D/T7208	8MM
MKSYSE			

## ETHERNET ADAPTER UPGRADE REQUIRED FOR AIX VER 3.2

## 1.2.7 ETHERNET ADAPTER UPGRADE REQUIRED FOR AIX VER 3.2

Record number: H096592

Device: D/T701X  
 Model: M  
 Tip key: 098  
 Date created: 092/02/23  
 Date last altered: A97/11/18

CUSTOMERS PLANNING TO INSTALL AIX VER 3.2 WILL BE ADVISED TO CONFIRM THE HARDWARE LEVEL OF THEIR ETHERNET ADAPTER(S). IF THE ETHERNET CARD HAS A ROS LEVEL 0008, 0009 OR 0010 THE CUSTOMER WILL BE ADVISED TO CONTACT THE IBM CUSTOMER ENGINEER REQUESTING ECA015.

\*\*\*\*\*  
 DO NOT REPLACE THE ETHERNET ADAPTER; BUT INSTEAD INSTALL ECA015  
 (ETHERNET EPROMS).  
 \*\*\*\*\*

ECA015 SHOULD BE INSTALLED ON ALL APPLICABLE SYSTEMS PRIOR TO  
 INSTALLATION OF AIX VERSION 3.2. FAILURE TO INSTALL ECA015  
 WILL EXPOSE THE CUSTOMER TO POTENTIAL ETHERNET PROBLEMS.

TO DETERMINE THE ADAPTER HARDWARE ROS LEVEL ENTER THE FOLLOWING  
 COMMANDS:

```
lsdev -C | grep ent (provides # of active ethernet adapters)
then
  lscfg -v -l entx (x represents the card # in prior command)
```

THE RESULTS OF THESE TWO COMMANDS WILL DISPLAY THE VITAL PRODUCT  
 DATA (VPD) FOR INSTALLED ETHERNET ADAPTER(S).

ECA015 IS AN "AS REQUIRED" ENGINEERING CHANGE TO UPGRADE EPROMS  
 ON SPECIFIC ETHERNET ADAPTERS. ORDER VIA NORMAL EC ORDERING  
 PROCESS. IN EMERGENCY SITUATIONS ORDER ECA015 "CODE A EXPEDITE".

## SAS KEYWORDS:


701XLAN	701XCOMM	701XHANG	701XIPL
701XECA	701XADAPT	701XADAPTCOMM	7012ECA
7013ECA	7015ECA	7016ECA	7018ECA
7012	7013	7015	701X
7016	7018		

## 1.2.8 ETHERNET RISER CARD JUMPER SETTING FOR 7012 MODELS 340 - 350

Record number: H097218

Device: D/T7012  
 Model: M  
 Tip key: 007  
 Date created: 092/03/12  
 Date last altered: A92/09/16

ETHERNET RISER CARD REQUIRE THE CORRECT JUMPER SETTINGS TO ENSURE ETHERNET OPERATION. THERE ARE 3 ROWS OF 8 JUMPER PINS. REFERENCING FROM THE TOP OF THE RISER CARD POSITION 1 IS THE TOP MOST ROW (FARTHEST AWAY FROM MICROCHANNEL I/O CONTACTS).



ALL 8 JUMPERS MUST BE FROM ROW 1 TO ROW 2 WHEN USING THICK CABLE  
 ALL 8 JUMPERS MUST BE FROM ROW 3 TO ROW 2 WHEN USING THIN CABLE  
 IF INSTALLING TWISTED PAIR ETHERNET CARD ASK CUSTOMER IF " LINK  
 INTEGRITY " WILL BE USED. THE SINGLE JUMPER MUST BE SET IN THE  
 RIGHT TWO PINS FOR LINK INTEGRITY TO BE " ON " OR THE LEFT  
 TWO PINS FOR LINK INTEGRITY TO BE " OFF " .



THIS INFORMATION WILL BE AVAILABLE IN THE NEXT RELEASE (04) OF  
 THE INSTALLATION SERVICE GUIDE SA23-2624-04.

THIS INFORMATION PERTAINS ONLY TO 7012 MODEL 340 AND MODEL 350

## SAS KEYWORDS:

7012ADAPT	7012ADAPTCOMM	7012LANS	701X
7012	RS6000	RS/6000	701XMISC
701XLAN	701XADAPT	701XADAPTCOMM	701XETHERNET
7012ETHERNET	701XJUMPERS	7012JUMPERS	701XRISER
7012RISER	701XADAPTOTH	7012ADAPTOTH	

## 1.2.9 FIRMWARE FOR GXX, JXX AND RXX SMP SYSTEMS

Record number: H161301

Device: D/T7012  
 Model: MG30  
 Tip key: 024  
 Date created: 096/08/05  
 Date last altered: A98/04/24

This note is to inform the field that the latest level of firmware (A9.50) is now available for distribution.

This new level of flash firmware includes the following changes:

## ENHANCEMENTS

-----

1. Firmware integration (common code for GXX, JXX and RXX)
2. 604 processor support
3. lgb memory support (stacked dimm)
4. Flash loading via a modem attached to a TTY (S2)
5. Additional power on tests
6. Improved power on tests  
Improved 409/022 SRN isolation
7. Improved diagnostic capability

## FIXES

-----

1. Hang conditions during boot phase of AIX at led299 caused by invalid ipl control block
2. Network boot fails with graphics card installed (G30 only)
3. Incorrect memory error callout with off line tests
4. Incorrect error message for LOPP condition when operating with redundant power supply (R30 only)
5. Incorrect SRN callout for fan failures (R30 only) i.e. 407/075
6. Unable to select slot 8 as the boot slot from the maintenance menu (R30 only)
7. Unable to configure X.25 in the 2nd MCA planar (R30 only)
8. Incorrect text when booting from network when network adapters are in slots 4-7 of bus0 or slots 0-7 of bus1
9. Network boot timeout:  
During a boot from a NIM server, the transfer file by TFTP fails. The boot request is correct and it begins listening for boot request packets. The server always replies, but during the transfer by TFTP it seems that there is a timeout and the TFTP fails.

## FIRMWARE INCOMPATIBILITY

-----

Before installing the latest level of firmware, two things must be determined.

1. Current level of firmware installed
2. Level of specific hardware currently installed

To determine the level of firmware, perform the following:

1. If the system is powered ON and AIX is operational, issue the following command at the prompt:  
lscfg -vl ioplanar0  
Refer to the heading "Device Specific (RM)". The first 4 characters in the RIGHTMOST number is the flash firmware level.
2. If STANDBY POWER is ON and the standby menu is displayed, (key MUST be in service mode), select option 0 "Display Configuration" and check the FLASH\_FW field for the current level.

## DETERMINING THE CURRENT HARDWARE LEVEL

-----

Before installing the new flash firmware, it is imperative that the current hardware level is verified to determine if an incompatibility exists. This current level of flash firmware will not work with downlevel hardware. The steps are different depending on the model of the machine.

## G30 STEPS

-----

1. If the system is powered on and AIX is operational, issue the following command:  
lscfg -vl sysplanar0
  - a. Refer to the heading "Part Number". This field contains the assembly part number. Record this number for reference in the next step.
  - b. Refer to the "Down level part number table" to compare the

- down level assembly part number with the assembly part number that was recorded in the previous step.
2. If the standby menu is displayed, select option 0 "Display Configuration" and check the hardware level. For example, the ELM card level will be shown under the field SP (system planar). Record this number and refer to the abovementioned table.
  3. If the system is powered off (no AC), check the fru/assembly part number of the elm by removing the card. Refer to the down level part number table to compare the down level fru/assembly part number with the fru/assembly part number of the card.

## J30 AND R30 STEPS

- 
1. If the system is powered on and AIX is operational, issue the following command:  
lscfg -vl ioplanar0
    - a. Refer to the heading "Part Number". This field contains the assembly part number. Record this number.
    - b. At the AIX prompt, execute the following command:  
lscfg -vl sif0
    - c. Refer to the heading "Part Number". This field contains the assembly part number. Record this number.
    - d. Refer to the "Down Level Part Number Table" to compare the down level assembly part number with the assembly part numbers that were recorded in the previous steps.
  2. If STANDBY POWER is ON and the standby menu is displayed, select option 0 "Display Configuration" and check hardware levels. IOD card level is indicated under the IOC field and SIB/SIF card level is under the SIB10 field. Record these numbers.
  3. If the system is powered off (no AC), check the fru/assembly part numbers of the IOD and SIF/SIB by removing the cards. Refer to the "Down Level Part Number Table" to compare the down level fru/assembly part number with the fru/assembly part number of the cards.

\*\*\*\*\*DOWN LEVEL PART NUMBER TABLE\*\*\*\*\*  
The table below indicates assembly part numbers to be used for compatibility checks and the ECA to be used for each upgrade. Read NOTE restrictions below each table.

ECA	TYPE	MODEL	NAME	FRU P/N	ASSEMBLY P/N
206	7012	G30	ELM	19H0228	19H0172,19H0369,19H0475
207	7015	R30	SIB	65G6131	11H8230,65G6108
207	7015	R30	SIB	11H8272	11H8245
207	7015	R30	IOD	19H0279	19H0304,19H0444,19H0463
208	7013	J30	IOD	19H0246	19H0303,19H0364,19H0462
208	7013	J30	SIF	19H0216	19H0385,19H0386,19H0460,19H0461

\*\*\*\*NOTE\*\*\*\* The above assemblies will probably contain flash firmware level 5.23 or 5.23P (R30); order appropriate ECA. DO NOT RE-FLASH.

ECA	TYPE	MODEL	NAME	FRU P/N	ASSEMBLY P/N
206	7012	G30	ELM	19H0228	19H0482,19H0498,35H8707,35H8709 35H8752
207	7015	R30	IOD	19H0279	19H0481,96G4401
208	7013	J30	IOD	19H0246	19H0480,96G4400

\*\*\*\*NOTE\*\*\*\* The above assemblies can accept flash firmware level 7.04/7.04P; the MES upgrade enables use of these parts for 604 machines.  
Also, if either the assembly part number or fru part number on the machine is on the above list, an incompatibility exists and the flash firmware cannot be updated until the appropriate fru(s) are installed in the machine.

The new level of firmware is available both on AIXTOOLS and SIL. There are two versions of the flash firmware images on AIXTOOLS and SIL. One is a binary image and the other is a DOS emtcopy binary image.

Refer to the README file for creating diskettes and installation instructions.

## SAS KEYWORDS:

7012	7013	7015	G30
J30	R30	SMP	FIRMWARE

FLASH  
JXX

9.22  
RXX

LEVEL

GXX

7012 RETAIN TIPS  
G30 ELM AND MRE MEMORY

1.2.10 G30 ELM AND MRE MEMORY

Record number: H024284

Device: D/T7012  
Model: MG30  
Tip key: 022  
Date created: 096/08/30  
Date last altered: A97/04/21

When replacing the system planar (ELM) on this machine, either for ECA206 or for regular maintenance, a problem may be encountered if MRE memory is installed. The ELM has standoffs that will NOT allow the MRE board to be installed. In order to install the memory board, the standoffs will have to be removed. This is done by removing a nut and washer from the UNDERSIDE of the ELM. If this hardware is removed, it should be given to the customer in case newer style memory is ordered in the future. Also, if this is checked ahead of time, it will prevent having to install the ELM twice.

SAS KEYWORDS:

7012/G30	G30	ELM	SYSTEM PLANAR
ECA206	STANDOFFS	MRE	MEMORY
SYSPLANAR	701X	SMP	

## 1.2.11 INVALID SIMM LOCATION FOR SRN'S 812/XXX OR 940/XXX

Record number: H125984

Device: D/T701X  
 Model: M  
 Tip key: 201  
 Date created: 095/01/12  
 Date last altered: A95/01/12

RISC6000 or 9076 (sp2) Some of the above SRN's, when encountered due to a SIMM error on a base memory card, will give invalid SIMM location information. SIMM errors are reported in the format 00-0x-00-0y, where x is the memory card location (A thru H) and y is the SIMM location (1 thru 8). The above SRN's are giving invalid SIMM locations on some models, giving letters for SIMM locations or leaving the SIMM location field blank. There is no way to translate this information into usable data. The Memory Card location is valid.

IF THE SIMM LOCATION IS INVALID USE THE FOLLOWING PROCEDURE TO ISOLATE THE PROBLEM:

Swap 4 SIMMs between the failing memory card and another card of the same size. The next failure will isolate the error to 4 SIMMs, depending on which memory card the failure now shows up on. Next swap 2 of the suspect SIMMs back to their original card. The next failure will isolate to 2 SIMMs. Swap 1 of these SIMMs back to the memory card it just came from and the next failure will identify the faulty SIMM.

## SAS KEYWORDS:

701X	D/T7012	D/T7013	D/T7015
7012	7013	7015	9076
SP2	MEMORY	SIMM	SRN812-XXX
SRN940-XXX	812-XXX	940-XXX	SRN812/XXX
SRN940/XXX	SRN940	SRN812	RS6000
RISC6000	D/T9076		

## LED288 HANG ON SMP CPU WITH EXPANSION UNIT ATTACHED

## 1.2.12 LED288 HANG ON SMP CPU WITH EXPANSION UNIT ATTACHED

Record number: H131122

Device: D/T701X  
 Model: M  
 Tip key: 242  
 Date created: 095/10/03  
 Date last altered: A96/11/08

LED288 on a 7013-J30 with a J01 expansion unit attached or 7012-G30 with a G01 expansion unit attached.

This LED hang can occur any time that NVRAM is corrupted i.e. if battery runs low and needs to be replaced, or fru containing NVRAM is replaced. If the machine hangs at LED288 or a checkstop occurs with an expansion unit attached use the following procedure first before replacing any parts.

The expansion unit must be unidentified to the cpu base unit.

1. All connections to the expansion unit made
2. Power applied to both the cpu and the expansion unit
3. cpu keymode switch in Service position
4. Type sbb at > sign to get standby menu
5. At standby menu type a "2" (set unit number)
6. The return message identifies the base unit a 0 and the expansion unit(s) as 1,2 etc. (done automatically by system and you will see 0-1-2 etc. displayed)

IF A NEW INSTALL FOLLOW THE INSTRUCTIONS IN THE "HARDWARE SETUP PROCEDURE" .

## SAS KEYWORDS:

7013 - J30	D/T7013J30	7013MODJ30	7013MODELJ30
J30	SMP	J01	RS6000
LED288	288	101/288	101-288
SRN101 - 288	SRN101/288	CONFIGURATION	EXPANSION
7012 - G30	D/T7012G30	7012MODG30	7012MODELG30
G01	G30	SMP	CHECKSTOP
SP2	9076		

1.2.13 LED8|-8 OR LED8T8

Record number: H122733

Device: D/T701X  
Model: M  
Tip key: 181  
Date created: 094/02/15  
Date last altered: A94/02/15

LED8T8 OR 8|-8 is an led indication that appears in the op panel display as an 8, the letter 'T' on its side, 8 or led8t8. This should be treated the same as an led185. To troubleshoot, use MAP1540 or minimum configuration. This error usually is the result of a defective cpu, system planar or memory. As noted, minimum configuration should be used to isolate the problem.

SAS KEYWORDS:

7011	7012	7013	7015
7018	RS6000	RISC6000	701X
D/T7011	D/T7012	D/T7013	D/T7015
LED8T8	8T8	LED 8T8	CPU
RISC	MEMORY	SYSTEMPLANAR	SYSTEM PLANAR

7012 RETAIN TIPS  
LED869 OR LED957 DURING IPL

1.2.14 LED869 OR LED957 DURING IPL

Record number: H067665

Device: D/T701X  
Model: M  
Tip key: 029  
Date created: 090/10/02  
Date last altered: A91/02/04

MACHINES AFFECTED: D/T7012, D/T7013, D/T7015, D/T7016

AUSTIN FSC HAS RECEIVED SEVERAL REPORTS OF LED 869 AND LED 957 HALTS DURING IPL. THE PROBLEM IS CAUSED BY REMOVING MEMORY CARDS AFTER AIX SOFTWARE HAS BEEN INSTALLED.

LED 869 WILL OCCUR WHEN ATTEMPTING TO IPL FROM A SCSI DISK DRIVE WHEN ONLY 8 MB OF MEMORY IS INSTALLED.

LED 957 WILL OCCUR WHEN ATTEMPTING TO IPL FROM A DIRECT BUS ATTACHED (DBA) DRIVE WHEN ONLY 8 MB OF MEMORY IS INSTALLED.

IF A CUSTOMER IS REPORTING ONE OF THE ABOVE SYMPTOMS, CHECK THAT MEMORY CARDS HAVE NOT BEEN REMOVED AFTER AIX WAS INSTALLED. IF YOU DETERMINE THAT THE CUSTOMER HAS NOT REMOVED MEMORY CARDS THEN FOLLOW NORMAL PROBLEM DETERMINATION PROCEDURES TO ISOLATE THE CAUSE OF THE PROBLEM.

SAS KEYWORDS:

701X	7012	7013	7015
7016	701XIPL	7012IPL	7013IPL
7015IPL	7016IPL	701XLED	7012LED
7013LED	7015LED	7016LED	LED869
LED957	RS6000	RS/6000	

## 1.2.15 LED888/102 700/XCX RUNNING 2.4.3 DIAGS

Record number: H124763

Device: D/T701X  
 Model: M  
 Tip key: 188  
 Date created: 094/07/29  
 Date last altered: A94/07/29

When running stand-alone diagnostics 2.4.3 and using a 3151 as a console be sure to hit the RETURN key and not the SEND key when identifying your terminal. If SEND is hit the machine may crash with an 888/102 700/xCx. This may cause someone to replace unneeded parts.

## SAS KEYWORDS:

LED888/102 700	888/102 700/XCX	888-102-700-XCX	LED888-102-700
D/T7006_ 7006	D/T7009 7009	D/T7011 7011	D/T7012 7012
D/T7013 7013	D/T7015 7015	D/T7018 7018	D/T7030 7030
DIAGS	DIAGNOSTICS	DISKETTES	CDROM
DIAGS2.4.3	2.4.3	RS6000	RISC6000
FLASHING LED888	FLASHING 888	3151	CONSOLE
IBM3151	888/102 700/0C4	888/102 700/0C0	888-102-700-0C0
888 - 102 - 700-0C4	888/102 700/0CX		

## LEVEL 2 CACHE CONNECTORS MISLABELED ON CPU PLANAR

## 1.2.16 LEVEL 2 CACHE CONNECTORS MISLABELED ON CPU PLANAR

Record number: H126786

Device: D/T7012  
 Model: M  
 Tip key: 012  
 Date created: 095/03/17  
 Date last altered: A97/04/15

There are two physical Level 2 cache connectors on the CPU planar. One is labeled "L1" and the other is labeled "L2" (L1 and L2 labels should not be interpreted as level 1 and level 2 cache). Connector "L1" should be "L2" and "L2" should be "L1".

This creates a problem when diagnostics are run because they will point to the wrong Level 2 cache location.

### SEE NOTE BELOW ###

If a fault exists on the Level 2 cache, the diagnostics will call out the following SRNs:

DIAGNOSTICS SRN	Diag FRU Callout	Actual Level 2 Cache FRU location
940-602	00-00-00-01	L2
940-602	00-00-00-02	L1
940-604	00-00-00-01	L2
940-604	00-00-00-02	L1

## NOTE:

Approximately 200 CPU cards are affected in 7012-39H, 7030-3CT, and SP2 machines.

To identify if a card has this problem it must satisfy the following criteria:

1. Assembly P/N88g3541 (on barcode label)
2. The level 2 cache connectors are labeled L1 and L2

## SAS KEYWORDS:

7012	7012/39H	7012MOD39H	7012MODEL39H
MODEL39H	MOD39H	7030	940/602
7030/3CT	7030MOD3CT	7030MODEL3CT	MOD3CT
MODEL3CT	SP2	SP2THIN	THINNODE
SRN904/602	LEVEL2	L2CACHE	CACHE
LEVEL 2			

## 1.2.17 MACHINE TYPE 1333 (4MM TAPE DRIVE)

Record number: H096323

Device: D/T701X  
 Model: M  
 Tip key: 191  
 Date created: 094/09/07  
 Date last altered: A94/09/07

Use the following procedure to remove a stuck cartridge in a 4mm tape drive m/t1333.

- 1) Turn the power switch to the OFF position
- 2) With the eraser end of a pencil or pen, apply pressure to the end of the cassette closest to the door. Lift gently to raise the end of the tape.
- 3) While maintaining pressure on the "edge" of the cassette turn the power switch to the ON position.
- 4) While continuing to apply pressure to the edge of the cassette press the EJECT button to dislodge the cassette.
- 5) After removing the cassette, turn the power switch to the OFF position.
- 6) Turn the power switch to the ON position to "recycle" the tape drive.

IF THIS TAPE DRIVE P/N93F5556 IS REPLACED IT "MUST" BE WRITTEN OFF TO M/T1333.

## SAS KEYWORDS:

M/T1333	M/T 1333	D/T1333	D/T 1333
7006	7008	7011	7012
7013	7015	D/T7006	D/T7008
D/T7011	D/T7012	D/T7013	D/T7015
RS6000	DICKENS	RISC	RISC
TAPE	4MM		

## 1.2.18 MEMORY CARDS AND SIMMS COMPATIBILITY

Record number: H122263

Device: D/T701X  
 Model: M  
 Tip key: 178  
 Date created: 094/01/10  
 Date last altered: A97/12/04

\*\*\*\*\*  
 !!!!!!!!!!!!!!!!!!! WARNING !!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!  
 \*\*\*\*\*

BE SURE TO CHECK THE ENTIRE CHART BEFORE USING P/N'S AS NEW  
 CARDS AND SIMMS HAVE BEEN ADDED....

Mem Card Type	Fru # Card #	Card Assm #s in MBs	Simm Upgrade in MBs	EC Lev lscfg -v	Model #s
S1	59f4433 594431	53f3089-8 53f3091-16	N/A	00	320/520/530 730/930/32h 52h
U1 not compatible with any other mem	59f4436	71f0855-32	N/A	XXXXXX	540 only
S1.5	81f8926 81f8924	81f8925-32 81f8927-64	N/A	00	320/520/530 730/930/32h
S3.1	65g1803 00g2205	00g2206-8 00g2209-16 00g2211-32 00g2213-64	32, 64, 128	20	340/350/53h 550/950
S3.2	65g1803 32g0101	32g0102-8 32g0103-16 32g0104-32 32g0105-64	32, 64, 128	20	340/350/53h 550/580/950
S3.3	65g1803 32g1846	32g1858-8 32g1859-16 32g1860-32 32g1861-64 43g0591-128	32, 64, 128	21	340/350/355 360/365/370 375/53h/55L 550/560/570 580/950/97b 98b/980
S4.5	65g1803 52g4801	65g1793-8 65g1799-16	32, 64, 128	33	58h/590/990
S4.5 256mb Downward compatible except with S1, S1.5 & U1	52g4801	65g1800-32 65g1801-64 65g1802-128			
S4.5 256mb Downward compatible except with S1, S1.5 & U1	52g4801	52g4729-256	N/A	34	58h/590/990
S4.6 255mb Downward compatible except with S1, S1.5 & U1	56g4729 88g3680	same as S4.5	N/A	34	58h/590/990
S5.0 base card	12h1331	12H1325			
S5.0 info only		12H1326 (32M - Populated Assy number) 12H1327 (64M - Populated Assy number) 12H1328 (128M- Populated Assy number) 12H1329 (256M- Populated Assy number)			

**7012 RETAIN TIPS**  
**MEMORY CARDS AND SIMMS COMPATIBILITY**

3.0 MEMORY SIMM MATRIX

Sim Type	FRU #	Sim P/N	Card Size
1mb	59f4581	23f8549	8mb
2mb	59f4582	68x6271	16mb
4mb	70f9973	68x6356	32mb
8mb	70f9976	68x6357	64mb
16mb	43g1796	32g8212	128mb
32mb (s4.5)	65g6452	64g2074	256mb 4.5 card
32mb S4.6 & S5.0	39H8312	33g0728	256mb 4.6 card & 5.0 card

4.0 MEMORY SIMM KIT & RETURN KIT MATRIX

Sim Kit Memory Size	Memory Upgrade Kit P/N	Return Kit P/N
8mb	N/A	52g4078
16mb	N/A	52g4079
32mb	65g3583	52g4080
64mb	65g3584	52g4081
128mb	65g3585	52g4082

SAS KEYWORDS:

701X	7012	7013	7015
7018	7012-32X	7013-52X	7013-53X
7013 - 54X	7013-55X	7013-56X	7013-57X
7013 - 58X	7015-92X	7015-93X	7015-95X
7015 - 97X	7015-98X	7015-99X	7013-59X
7012 - 34X	7012-35X	7012-36X	7012-37X
MOD32H MOD34H	MOD53H MOD55L	MOD58H	MOD98H
MACH701X	D/T7012	D/T7013	D/T7015
RS6000	MEMORY	COMPATIBILITY	

## NIM INSTALL COMPATABILITY FOR 10/100 ETHERNET ADAPTER

## 1.2.19 NIM INSTALL COMPATABILITY FOR 10/100 ETHERNET ADAPTER

Record number: H1665

Device: D/T701X  
 Model: M  
 Tip key: 322  
 Date created: 097/06/12  
 Date last altered: A98/01/15

To enable Network Install Manger ( NIM ) installs using the 10/100 Mb Ethernet MC adapter (FC #2964 and FC #2994) a minimum level of IP ROS emulation/Firmware code is required as follows:

- The following systems require code level IPLROM.image.9705071651 or higher:
  - D/T7006: 41T 41W 42T 42W
  - D/T7012: 390 39H
  - D/T7013: 590 591
  - D/T7015: 99J 99K R20 R24
  - D/T7030: 3BT 3CT
- If the above code is not available then the normal NIM IPLROS Emulation diskette can be used. Note: PTFs might be needed on the NIM server to complete installation. Contact software support if needed.
- The following systems require firmware level VER1.2 LVL2.07 or above:
  - D/T7009: C10 C20
  - D/T7013: 595
- The following systems require firmware level C9.43 or above:
  - NOTE: 7012/G30 with 601 processors does NOT support C9.43
  - D/T7012: G30 (With 604 Processors Only) G40
  - D/T7013: J30 (604 Upgrade only) J40 J50
  - D/T7015: R30 (604 Upgrade only) R3U R4U R40 R50

## SAS KEYWORDS:

701X	SP2	SMP	IPL
ROM	FIRMWARE	IPLROM	VERSION
LEVEL	LVL		

## 1.2.20 ON CARD LED BLINK CODES FOR SCSI-2 ADAPTER 4-6 OR 4-7

Record number: H104172

Device: D/T9076  
 Model: M  
 Tip key: 023  
 Date created: 096/04/17  
 Date last altered: A96/04/17

Meaning of On Card LED Blinking and Codes The on card LED will be ON while the adapter is running through the PowerOnSelfTest. If POST completes successfully, the LED will go OFF. If your system won't boot and your boot adapter is a 4 - 6 or 4 - 7 AND the LED stays ON, disconnect any external devices and run diagnostics to verify that the adapter and not an external device/s in the configuration is the cause of the problem. If the LED is blinking in a periodic fashion (on-off-on off-pause-on-off-on-off etc) it means that one of the POST tests has failed. The system may boot in this case, but will probably not function correctly. Diagnostics should be run to verify the failure or isolate the problem in the system configuration. The flashing LED blink codes are as follows:

Number of Flashes	Meaning
1 =	80C186 ROM test failed
2 =	Local RAM test failed
3 =	Terminator power circuit breaker open (PTC failure)
4 =	80C186 Internal peripheral test failed
5 =	Local transfer bus failed
6 =	No value given N/A
7 =	System interface control chip test failed
8 =	SCSI internal interface test failed
9 =	No value given N/A
10 =	SCSI external interface test failed

A blink code of 3, 8, or 10 may indicate a configuration problem like a shorted cable or bad device, or duplicate SCSI addresses on the same bus. Refer to the SCSI-2 Fast / Wide Problem Problem Determination Procedures in the MAPs section of the Common Diagnostics & Service Guide for further troubleshooting guidelines.

During normal operation the device driver may issue a command reset to the adapter, when this occurs you will see the LED blink briefly.

## SAS KEYWORDS:

7012	7013	9076	SP2
D/T7012	D/T7013	D/T9076	RISC6000
RISC6K	RISC		

## 1.2.21 PROBLEMS WITH AIX 3.2 MEMORY SCRUBBING FEATURE

Record number: H101858

Device: D/T701X  
 Model: M  
 Tip key: 132  
 Date created: 092/10/08  
 Date last altered: A92/10/12

MACHINES AFFECTED: D/T7011, D/T7012, D/T7013, D/T7015, D/T7016

THE FOLLOWING PROBLEMS ARE ASSOCIATED WITH THE MEMORY SCRUBBING FEATURE PROVIDED IN AIX VERSION 3.2 AND ABOVE.

1. INTERMITTENT LED888 SYSTEM HALTS.
2. SYSTEM HANGS APPROXIMATELY 3-4 HOURS AFTER IPL. NO ERRORS ARE LOGGED IN THE ERROR LOG AND THE LED DISPLAY REMAINS BLANK. IF A SYSTEM DUMP IS ATTEMPTED BY TURNING THE KEY TO THE SERVICE POSITION AND PRESSING THE RESET BUTTON, LED100 WILL APPEAR IN THE LED DISPLAY. THIS SYMPTOM HAS BEEN REPORTED ON SYSTEMS WITH MORE THAN 128MB OF MEMORY INSTALLED.
3. ERROR LOG ENTRIES AND CONSOLE ERROR MESSAGES REPORTING DEFECTIVE MEMORY. IN SOME CASES THE AMOUNT OF DEFECTIVE MEMORY CONTINUES TO INCREASE EACH TIME DIAGNOSTICS ARE RUN. REPLACEMENT OF HARDWARE DOES NOT CORRECT THE PROBLEM.

THESE THREE PROBLEMS ARE CURRENTLY BEING INVESTIGATED. IF THESE OR OTHER UNUSUAL SYMPTOMS ARE BEING REPORTED AND AIX VERSION 3.2 OR ABOVE IS INSTALLED, MEMORY SCRUBBING SHOULD BE TURNED-OFF.

DO THE FOLLOWING TO CHECK/TURN-OFF MEMORY SCRUBBING.

1. Login as root
2. ENTER smit AT AIX COMMAND PROMPT
3. SELECT System Environments
4. SELECT Change / Show Characteristics of Operating System
5. CHANGE Enable memory SCRUBBING to FALSE
6. Press ENTER

After turning-off memory scrubbing the system should be shutdown and rebooted to clear the defective memory map created during memory scrubbing.

## SAS KEYWORDS:

701X	7011	7012	7013
7015	701XLED	7011LED	7012LED
7013LED	7015LED	701XHANG	7011HANG
7012HANG	7013HANG	7015HANG	7016
7016LED	7016HANG		

## RELOCATION KIT PART NUMBERS FOR RISC SYSTEMS

## 1.2.22 RELOCATION KIT PART NUMBERS FOR RISC SYSTEMS

Record number: H096004

Device: D/T701X  
 Model: M  
 Tip key: 093  
 Date created: 092/01/13  
 Date last altered: A93/04/19

BELOW ARE THE PART NUMBERS FOR THE RISC SYSTEM/6000 RELOCATION  
 KITS (PACKAGING):

M/T	PART NUMBER
D/T7012	- P/N58F2891
D/T7013	- P/N58F2890
D/T7015	- P/N72X5992
D/T7016	- P/N59F3854

## ORDERING PROCEDURES:

THESE RELOCATION KITS CAN BE ORDERED VIA REAL TIME SYSTEM (RTS).  
 FOR QUESTIONS, REFER TO D/L FDS91-058-NS051 OR FDS91-075-NS062  
 OR THE BRANCH OFFICE MANUAL SECTION 1, SUBSECTION 12.

## SAS KEYWORDS:

701X	RS6000	RS/6000	7012
7013	7015	7016	701X PART
7012 PART	7013 PART	7015 PART	7016 PART
701XMISC	PACKING	PACKAGING	701X PACKING
7012PACKING	7013PACKING	7015PACKING	701X SHIPPING
7012SHIPPING	7013SHIPPING	7015SHIPPING	701X PACKAGING
7012PACKAGING	7013PACKAGING	7015PACKAGING	

## REMINDERCOLON. RESET DATE AND TIME AFTER DISCONNECTING BATTERY

## 1.2.23 REMINDER&amp;COLON. RESET DATE AND TIME AFTER DISCONNECTING BATTERY

Record number: H09180

Device: D/T701X  
 Model: M  
 Tip key: 089  
 Date created: 091/12/13  
 Date last altered: A92/06/02

MACHINES AFFECTED: D/T7012, D/T7013, D/T7015, D/T7016, D/T7018

SOME SOFTWARE APPLICATIONS (IE. CATIA) MAY NOT RUN IF THE SYSTEM DATE AND TIME IS NOT SET CORRECTLY.

THE LITHIUM BATTERY, P/N23F0168, MAINTAINS THE TIME-OF-DAY CLOCK AND THE CONTENTS OF NVRAM WHEN THE SYSTEM IS POWERED-OFF. THE DATE AND TIME MUST BE RESET ANYTIME THE BATTERY IS REPLACED OR DISCONNECTED FOR MORE THAN 30 SECONDS.

THE DATE AND TIME CAN BE RESET BY USING THE FOLLOWING PROCEDURE:

1. ENTER 'smit date' (IN LOWER CASE) ON THE COMMAND LINE.
2. UPDATE THE DATE AND TIME FIELDS AND PRESS ENTER.

IF YOU DO NOT HAVE ACCESS TO THE ROOT PASSWORD, BE SURE TO REMIND THE USER THAT THE DATE AND TIME MUST BE RESET.

## SAS KEYWORDS:

701X	7012	7013	7015
7016	7018	701XMISC	7012MISC
7013MISC	7015MISC	7016MISC	7018MISC
RS6000	RS/6000	701XPWR	7012LOGIC
701XLOGIC	7012PWR	7013LOGIC	7013PWR
7015PWR	7015LOGIC		

## SCSI-2 DIFFERENTIAL ADAPTER FAILURE ISOLATION PROCEDURE

## 1.2.24 SCSI-2 DIFFERENTIAL ADAPTER FAILURE ISOLATION PROCEDURE

Record number: H20465

Device: D/T701X  
 Model: M  
 Tip key: 150  
 Date created: 093/02/19  
 Date last altered: A95/03/30

BEFORE REPLACING THE SUSPECTED SCSI-2 DIFFERENTIAL ADAPTER, THE POSITIVE TEMPERATURE COEFFICIENT (PTC) SHOULD BE CHECKED. THE PURPOSE OF THIS PTC IS TO PROTECT THE EXTERNAL BUS. THE PTC CAN BE TRIPPED BY A CABLE, TERMINATOR, OR ANY DEVICE ATTACHED TO THE DIFFERENTIAL BUS.


A FAULT CAUSES AN INCREASE IN PTC RESISTANCE, AND THE RESULTANT HEAT TRIPS THE PTC. REMOVING THE FAULT AUTOMATICALLY ALLOWS THE PTC TO RESET (WITHIN 15 MINUTES THE PTC SHOULD RESET).

\*\*\*\*\*  
 DO NOT REPLACE THE SCSI-2 DIFFERENTIAL ADAPTER BECAUSE THE PTC HAS TRIPPED. USE THE FOLLOWING ISOLATION PROCEDURE TO LOCATE THE CABLE, TERMINATOR, OR DEVICE ON THE EXTERNAL BUS CAUSING THE PTC TO TRIP.  
 \*\*\*\*\*

\*\*\*IMPORTANT\*\*\* ENSURE THAT THE SYSTEM POWER AND ALL EXTERNALLY ATTACHED DEVICE POWER IS TURNED OFF. ALL TESTING WILL BE DONE WITH POWER OFF, USING DIGITAL OHMMETER FOR RESISTANCE READINGS.

STEP 1. WITH THE SCSI-2 DIFFERENTIAL ADAPTER STILL INSTALLED IN THE SYSTEM UNIT (EXCEPT IN MODEL 9XX, WHERE THE ADAPTER, FOR ACCESSIBILITY, SHOULD BE REMOVED AND THE EXTERNAL CABLE REMAIN ATTACHED), VERIFY THAT THE PTC IS COOL AND IS IN A LOW RESISTANCE STATE (200 MILLIOHMS OR LESS) BY CHECKING WITH A DIGITAL OHMMETER.

STEP 2. LOCATE BELOW DIODE D1 AND CONNECT THE (+) POSITIVE OHM-METER LEAD TO THE CATHODE OF D1 (THE END NEAREST THE PTC F2).  
 LOCATE BELOW OCILLATOR Y1 AND CONNECT THE (-) NEGATIVE OHMMETER LEAD TO THE CAN OF Y1.



STEP 3. IF BOTH DIFFERENTIAL TERMINATORS ARE INSTALLED ON THE ENDS OF THE SCSI-2 BUS (TWO TERMINATORS ON THE ADAPTER U8 AND U26 AS WELL AS THE TERMINATOR AT THE LAST DEVICE ON THE BUS), THE RESISTANCE SHOULD INDICATE BETWEEN 19 AND 25 OHMS.

\* IF RESISTANCE IS BETWEEN 19 AND 25 OHMS THERE IS NO APPARENT CAUSE FOR THE TRIPPED PTC.

\* IF RESISTANCE IS GREATER THAN 25 OHMS, ONE OF THE BUS END TERMINATORS IS MISSING AND SHOULD BE REPLACED.

\* IF RESISTANCE IS LESS THAN 19 OHMS, TROUBLE SHOOT THE SYSTEM BY DISCONNECTING CABLES, TERMINATORS AND THE DEVICES ATTACHED TO THE BUS UNTIL THE CAUSE OF THE LOW RESISTANCE IS FOUND.

PROBABLE TRIPPED PTC CAUSES:

1. MORE THAN TWO TERMINATORS ON THE BUS.
2. A SHORTED TERMINATOR OR CABLE. (CHECK FOR BENT PINS)
3. INTERMITTENT PTC TRIPPING MAY BE DUE TO A SHORTED CABLE OR IMPROPERLY SEATED CABLE CONNECTOR.
4. A SHOTED DEVICE
5. MISSING ON CARD TERMINATORS U8 AND U26. (TERMINATORS SHOULD

**7012 RETAIN TIPS**

**SCSI-2 DIFFERENTIAL ADAPTER FAILURE ISOLATION PROCEDURE**

BE REMOVED ONLY ON INCREASED AVAILABILITY CONFIGURATIONS).

6. HOT PLUGGING SCSI CABLES MAY TRIP PTC.

SAS KEYWORDS:

RISC	RISC/6000	701X	7013
7012	7015	7016	D/T701X
D/T7012	D/T7013	D/T7015	D/T7016

## 1.2.25 SCSI-2 F/W CONTROLLERS (ALL VARIETIES) MAY CAUSE PROBLEMS

Record number: H133050

Device: D/T701X  
 Model: M  
 Tip key: 258  
 Date created: 096/03/13  
 Date last altered: A96/03/18

## \*\* MACHINES AFFECTED \*\*:

All M/T that use Corvette (SCSI-2 F/W), including integrated versions.

## \*\* PROBLEM \*\*:

The Corvette SCSI-2 F/W Controller contains a chip called Malibu which is used to interface with the MicroChannel.

A problem was found with a certain datecode of Malibu that can cause system problems. The datecode is printed on the chip itself (NOT on the card/assy barcode). The Malibu chip contains three lines of markings. The first line should have the chip p/n (61G2323). Skip the second line. The datecode is printed on the third line and the following datecodes are suspect:

1Q010013N  
 1Q010023N  
 1Q03K023N  
 1Q04T003N  
 1Q06K013N

The location of the Malibu chip on the card/assy varies depending on which version of the controller you have. Here is a list of the U-location on the card/assy of the Malibu chip for each controller type. The U number is silkscreened on the card assembly.

SCSI-2 F/W Controller Type	FRU p/n	U-location
* Integrated	52G4325	U60
MicroChannel SE	11H3600	U5
MicroChannel DE	11H7660	U13
Enhanced Microchannel DE	52G3380	U16

Note (\*): The Integrated SCSI-2 F/W controller is the one on the I/O planar of the 7012-380/390/39H and 7012-3AT/3BT/3CT systems.

Although you may have one of the suspect datecodes, be aware that this may not be your problem. The entire datecode is not bad, but because of this, the whole lot is suspect. If you have any of the symptoms below, keep in mind the SCSI-2 F/W adapter may be the problem to assist in Problem Determination.

## \*\* SYMPTOMS \*\*:

There are three types of symptoms you may see....

## 1) Checkstops

For the 7012/7013/7015 boxes, analysis of the checkstop file will show an SCU (SIO BUS 0 PARITY, or SIO BUS 1 PARITY) checkstop occurred.

On the 7006/7009/7011 boxes, a checkstop cannot be decoded further.

On the SMP boxes, you will get a "Data Bus Parity Error" checkstop.

## 2) System Hang/Unresponsive

The system may hang (with no other symptoms) or it may be unresponsive to any inputs typed in. In the latter case, you may enter a simple command like 'ls', but will receive no response. You can usually Ctl-C to break out to another prompt, but any other command will not produce any responses.

## 3) DMA\_ERR in the Error Log

You may periodically see DMA\_ERR in the error log. The "CHANNEL UNIT ADDRESS" will point to the arbitration level of the SCSI-2 F/W Controller.

## \*\* WORKAROUND \*\*:

None

## \*\* PERMANENT FIX \*\*:

**7012 RETAIN TIPS****SCSI-2 FW CONTROLLERS (ALL VARIETIES) MAY CAUSE PROBLEMS**

Replace the card/assy if you suspect this is your problem.  
Insert a note with the suspect card/assy when returning it to  
Austin with the words "Bad Malibu datecode lot".

**SAS KEYWORDS:**

7006	7008	7009	7011
7012	7013	7015	FAST/WIDE
F/W	CORVETTE	MALIBU	CHECKSTOP
HANG	DMA_ERR	SCSI-2	SCSI2
I/O	INTEGRATED	U60	U5
U13	U16	D/T7006	D/T7008
D/T7009	D/T7011	D/T7012	D/T7013
D/T7015			

1.2.26 SMP BUMP CONSOLE FLAG

Record number: H125985

Device: D/T701X  
Model: M  
Tip key: 202  
Date created: 095/01/12  
Date last altered: A98/05/05

- 1) SMP's are shipped with the BUMP console DISABLED. Because of this, when first booting your system, you will see LED 165 on the LED display for about 4 minutes, indicating that tests are being run. Since the BUMP CONSOLE is shipped as disabled, there will be nothing displayed on the BUMP CONSOLE. To enable the BUMP CONSOLE, the flag will have to be enabled from the STANDBY MENU. The flag will then stay enabled until disabled from the menu.

According to the MAPs in the Diagnostic Information for Micro Channel Machines (SA38-0532-03) on page 2-5 it now states that on an SMP system the LED165 may display for about 30 minutes.

- 2) The default value of the BUMP Console Flag is incorrect in the manuals. As stated above, the flag is set to Disabled as the default, it is listed as Enabled in the documentation. Below are the locations where this information is listed incorrectly.

7012 G Series Service Guide	-	Pg A-13
7012 G Series Operator Guide	-	Pg 3-12
7013 J Series Service Guide	-	Pg 2-12
7013 J Series Operator Guide	-	Pg 3-12
7015 Mod R30 CPU Encl. Service Guide	-	Pg 2-13
7015 Mod R30 CPU Encl. Operator Guide	-	Pg 3-13

SAS KEYWORDS:

7012/G40	7013/J40	7015/R40	7015/R40
D/T7013/J30	D/T7015/R30	7012MODG30	7013MODJ30
7013MODR30	G30	J30	R30
7012/G30	7013/J30	7013/R30	7012G30
7013J30	7015R30	RS6000	RISC6000
7012	7013	7015	SMP
9076	SP2	7013/J50	7015/R50
D/T7012	D/T7013	D/T7015	D/T701X
701X			

## 1.2.27 3153 INFO&amp;COLON. MARKETING REFERENCE GUIDE (G520-9415)

Record number: H16288

Device: D/T3153  
 Model: M  
 Tip key: 016  
 Date created: 097/05/29  
 Date last altered: A98/03/19

A 30-page 3153 Marketing Reference Guide (G520-9415) is available for IBM Customers, IBM Representatives and IBM Business Partners. The 3153 Marketing Reference Guide contains:

- 3153 Feature/Function Information
  - Communication and Parallel Ports
  - Dual Session
  - Programmable Keys
  - Setup Menu
  - Character Sets and Code Pages
- 3153 Keyboards and Keyboard Languages
- 3153 Ordering Information
- 3153 Warranty/Service/Maintenance Information
- 3153 Model, Part Number Information (Worldwide)
- 3153 Technical Specifications Information
  - Communication and Parallel Ports
  - Screen Formats
  - Physical
- 3153 Host/Printer Cabling/Communication Information
  - RS/6000, AS/400
- 3153 Recommended Setup Values/Configuration Information
  - RS/6000, AS/400, 3745, 4690

The 3153 Marketing Reference Guide is a great technical and sales support document.

To obtain a copy of the 3153 Marketing Reference Guide via:

IBM Market Tools (MKTTOOLS):

- Enter the follow OV/VM Command:  
 TOOLS SENDTO USDIST MKTTOOLS MKTTOOLS GET G5209415 PACKAGE

IBMFAX Information Service:

- call 1 - 800-IBM-4FAX (US only) and request document #5704
- IBMFAX intranet: <http://w3.ibmfax.ibm.com>

IBM PC Company Fax System:

- call 1 - 800-IBM-3395 (US only) and request document #10005
- call 1 - 919-517-0011 (Worldwide - enter country code) and request document #10005

IBM Austin Intranet:

<http://w3.rs6000.ibm.com/mktmat>

IBM Canadian AIX Support Centre Intranet:

<http://w3.toraix.can.ibm.com/hdw/menu/3153.mnu>

## SAS KEYWORDS:

D/T3153	7006	7015	3153
7008	7024	MARKETING	7009
7025	REFERENCE	7010	70XX
GUIDE	7011	700X	RS/6000
7012	701X	RS6000	ATTACHMENT
702X	AS/400	CONFIGURE	3745
AS400	CONFIGURATION	4680	G5209415
4690	SCO	UNIX	OPENSERVER
D/T701X	D/T70XX	D/T702X	SETUP
CABLING	INFO	INFORMATION	GENERAL
D/T7006	D/T7008	D/T7009	D/T7010
D/T7011	D/T7012	D/T7015	D/T7024
D/T7025	D/T4680	D/T4690	SERVER
H16288	PART	PARTS	WARRANTY
SERVICE	SPECIFICATIONS	CABLING	ATTACH
ATTACHMENT	AIX	OS400	OS/400
HOST	PRINTER	CONSOLE	HELP
RISC	RISC/SYSTEM		

1.2.28 5081,6091,POWERDISPLAYS 16,17 DISPLAYS

Record number: H006167

Device: D/T701X  
 Model: M  
 Tip key: 041  
 Date created: 090/12/13  
 Date last altered: A93/12/17

IBM 5081's, 6091's, & POWERDISPLAYS MAY DISPLAY 2 VERY FINE HORIZONTAL LINES ACROSS THE SCREEN LOCATED APPROXIMATELY 1/3 AND 2/3 OF THE DISTANCE FROM THE TOP OF THE SCREEN.

AT "NORMAL VIEWING DISTANCE", THESE HORIZONTAL LINES ARE NOT VISIBLE, AND ARE ONLY SEEN UPON CLOSE INSPECTION WHEN A FULL WHITE BACKGROUND FIELD DISPLAY IS USED.

THE HORIZONTAL LINES ARE NOT A DEFECT. NO PARTS SHOULD BE REPLACED IN AN ATTEMPT TO CORRECT THIS PERCEIVED PROBLEM. THE HORIZONTAL LINES ARE THE RESULTS OF THE TECHNOLOGY USED IN THE MANUFACTURING OF THE 5081 AND 6091 DISPLAYS. THE HORIZONTAL LINES ARE NOT THE RESULTS OF A FAILING FRU AND/OR MANUFACTURING DEFECT.

REPLACING DISPLAY ADAPTERS IN THE RISC SYSTEM/6000 OR FRU'S IN 5081'S, 6091'S, AND POWERDISPLAYS WILL NOT REMOVE THE HORIZONTAL LINES  
 MACHINES AFFECTED: D/T7012, D/T7013, D/T7015, D/T7016, D/T5081, D/T6091. POWERDISPLAYS 16 AND 17

## SAS KEYWORDS:

5081DISP	6091DISP	DISPLAY	701X
701XDISP	701XADPT	6091ADPT	5081ADPT
701XSYSADPT	701X	7012	7013
7015	7016	RS6000	RS/6000
POWERDISPLAY	POWER DISPLAY		

1.2.29 540MB DISK DRIVE - END OF MANUFACTURING

Record number: H163205

Device: D/T701X  
 Model: M  
 Tip key: 344  
 Date created: 098/03/30  
 Date last altered: A98/03/30


Due to the End of Manufacturing of the 540MB disk drive, P/N51G8237 will sub to a different drive. The replacement drive that will be used when the sub takes place will be the 2.2GB drive, P/N74G6996. The form factor will remain constant, however the address jumper setting will be different. Use the following table when setting the address jumpers on the replacement drive.

\*\*\*\*\*


2.2GB (new replacement)  
 P/N74G6996

VALID ADDRESSES

(end view)




Address	Jumper 2	Jumper 1	Jumper 0
0	OFF	OFF	
1	OFF	OFF	ON
2	OFF	ON	OFF
3	OFF	ON	ON
4	ON	OFF	OFF
5	ON	OFF	ON
6	ON	ON	OFF



\*\*\*\*\*

540MB (old drive)  
 P/N51G8237

VALID ADDRESSES



Address	Jumper 5 - 6	Jumper 3 - 4	Jumper 1 - 2
0	OFF	OFF	OFF
1	OFF	OFF	ON
2	OFF	ON	OFF
3	OFF	ON	ON
4	ON	OFF	OFF
5	ON	OFF	ON
6	ON	ON	OFF

(top view)

\*\*\*\*\*

Note: The 540MB drive was use in the following RS6000 Machine types. 7006, 7011, 7012 and 7013.

SAS KEYWORDS:

710X	RISC	RS6000	DISK
7013	7012	7011	7006
D/T7006	D/T7011	D/T7012	D/T7013

## 1.2.30 7012 AND 7030 MEMORY CARDS

Record number: H126622

Device: D/T7012  
 Model: M  
 Tip key: 011  
 Date created: 095/03/07  
 Date last altered: A95/10/02

You can physically install an S3.x memory card in these systems. Even though we officially support S4.5 memory, or greater, on these systems, there is a potential for someone to put S3.x in. We have found the S3.3 cards installed in several instances. They can possibly result in random checkstops causing a reboot of the machine. Another symptom is that the customer may get a 15% INCREASE in processing speed with S3.x memory. Although this is good (from the customer's viewpoint), it is unstable (and unsupported).

The deskside (7013) and rack (7015) models that require memory cards at S4.5 or higher, have a physical interlock in their design to prevent plugging in lower level cards, but the desktops (7012) do not.

## SAS KEYWORDS:

D/T7012	7012MOD380	7012MOD390	7012MOD39H
D/T7030	7030MOD3AT	7030MOD3BT	7030MOD3CT
7012 - 380	7012-390	7012-39H	7030-3AT
7030-3BT	7030-3CT	7012/380	7012/390
7012/39H	7030/3AT	7030/3BT	7030/3CT
3AT	3BT	3CT	380
390	39H	MEMORY	3.3
4.5	CHECKSTOPS	CHECKSTOP	S3.3
7012	7030	RS6000	RISC

## 1.2.31 7012 G30 MOUSE AND KEYBOARD SUPPORT

Record number: H131557

Device: D/T7012  
Model: M  
Tip key: 014  
Date created: 095/11/03  
Date last altered: A96/11/11

WHEN INSTALLING A GRAPHICS ADAPTER INTO THE 7012 G30, IN ORDER  
FOR THE KEYBOARD AND MOUSE TO WORK, THE FOLLOWING MUST BE  
INSTALLED:

KEYBOARD/MOUSE CARD ASSEMBLY P/N11H3890  
SYSTEM MUST BE AIX VER 4.1.3 OR HIGHER

## SAS KEYWORDS:

7012 G30	7012MODG30	7012MODELG30	4.1.3
V4.1.3	AIX4.1.3	KEYBOARD	MOUSE
SMP	GRAPHICS	7012-G30	7012/G30
RS6000	RISC	SP2	9076

## 1.2.32 7012 WON'T BOOT TO DIAGNOSTICS FROM DISK

Record number: H086502

Device: D/T7012  
Model: M  
Tip key: 003  
Date created: 090/11/08  
Date last altered: A92/10/07

7012'S THAT ARE CONFIGURED WITH A SCSI ADAPTER AND AT LEAST ONE 120MB DISK DRIVE MAY NOT LOAD DIAGNOSTICS FROM THE DISK DRIVE WHEN THE SYSTEM IS BOOTED WITH THE KEY IN THE SERVICE POSITION. DIAGNOSTICS WILL, HOWEVER, LOAD AND RUN IN CONCURRENT MODE BY LOGING IN AS ROOT OR SUPERUSER AND ENTERING 'DIAG' AT THE COMMAND LINE.

TO CORRECT THIS PROBLEM, IT MAY BE NECESSARY TO CHANGE THE BOOTLIST CONTAINED IN NVRAM. TO DO THIS, HAVE THE CUSTOMER LOGIN AS ROOT AND TYPE THE FOLLOWING AT THE AIX COMMAND LINE:

```
BOOTLIST -M SERVICE FD RMT CD BADISK SCDISK  
(ALL ENTERED IN LOWER CASE).
```

THIS CHANGES THE ORDER THE DRIVES ARE SEARCHED WHEN THE KEY IS IN THE SERVICE POSITION TO FLOPPY DRIVE FIRST, REMOTE DRIVE SECOND, CD ROM DRIVE THIRD, DIRECT BUS ATTACHED DRIVE FOURTH, AND SCSI ATTACHED DRIVE FIFTH.

## SAS KEYWORDS:

7012	701X	7012DIAG	7012MISC
701XDIAG	701XMISC	701XDISK	7012DISK

7012 RETAIN TIPS

7012 397 39F FIRMWARE UPDATE FOR SYSTEM PLANAR

1.2.33 7012 397 & 39F FIRMWARE UPDATE FOR SYSTEM PLANAR

Record number: H161546

Device: D/T7012
Model: M397
Tip key: 026
Date created: 097/10/24
Date last altered: A97/10/24

At this time there is no new Flash firmware for the System Planar. This RETAIN tip will be updated whenever a Flash Firmware change occurs. Please reference this RETAIN tip every time you replace this part to see if any flash change has occurred.

The following note will be included in the FRU box. This note will be used so the service representative can identify the latest level of microcode, and upgrade if needed.

\* \* \* \* \*
The Flash memory on this part contains "down loadable" firmware at the latest level available on the day the part was shipped to field stock. NEWER FIRMWARE LEVELS MAY EXIST. Depending upon the "date of manufacture" of your customer's machine, it may have a more current level of firmware than that contained on this part. To ensure proper operation of your customer's machine you MUST review and adhere to the information and procedures outlined in RETAIN TIP \_\_\_\_\_ before installing this part.
\* \* \* \* \*

SAS KEYWORDS:

701X 7012 397 39F
FIRMWARE FLASH UPGRADE PLANAR

## 1.2.34 7012-G30 CPU AND MEMORY CARD REPLACEMENT PROCEDURES

Record number: H13188

Device: D/T7012  
Model: M  
Tip key: 013  
Date created: 095/06/20  
Date last altered: A96/11/08

The 7012 - G30 can be somewhat prone to bending pins on the ELM card and/or CPU and memory cards during removal/replacement. To minimize this risk it is recommended that the CPU and memory cards only be replaced on machines which are laid on the side. With the machines on the side rather than in the upright position you have the best access to these cards. It is still imperative that the card extraction tools be used to extract these cards.

## SAS KEYWORDS:

7012 - G30	7012/G30	7012MODG30	7012MODELG30
7012	G30	SMP	RISC
RS6000	RISC6000	TOOL	CPU
MEMORY	SP2	9076	

## 1.2.35 7012-G30 DISK POWER CABLE

Record number: H132519

Device: D/T7012  
Model: M  
Tip key: 015  
Date created: 096/02/02  
Date last altered: A97/04/15

D/T7012/G30 When going from 2 hard disks to 4 you must order a six drop internal scsi cable p/n11h3929 and "2" power "Y" cables p/n32g0218

## SAS KEYWORDS:

7012 - G30

7012/G30

7012MODG30

7012MODELG30

G30

SMP

Y CABLE

SCSI CABLE

POWER

DISKS

DISK

UPGRADE

## 1.2.36 7012/3XX DOCUMENTATION ERRORS SA23-2624-XX

Record number: H126141

Device: D/T7012  
 Model: M  
 Tip key: 010  
 Date created: 095/01/25  
 Date last altered: A97/05/06

SA23 - 2624 - 00 7012 Install &amp; Service Guide

- 1) Page 5 - 5: Index Number 1 shows FRU p/n52G4128 for the planar board. The correct FRU is p/n52G4325.
- 2) Page 5 - 9: Index Number 8 shows FRU is p/n88G3983. The correct FRU should be p/n88G3991.
- 3) Page 5 - 8 and 5-9 the drawing shows Item 8 pointing to two different parts (the 3 digit LED display and the Power Button) the 3 digit LED display is p/n00g2230.

SA23 - 2624 - 06

- 1) Page 5 - 10: Ref 10 power supply p/n32g0005 is incorrect. Ref 10 power supply should be p/n91f0844

SA23 - 2624 - 07

- 1) Page 5 - 13: Missing DASD cage (same as in 7030) p/n52g4906
- 2) Page 5 - 7: Missing Voltage Regulator p/n11h3747
- 3) Page 5 - 7: Ref 13 Front Bezel for the 380,390,39H p/n51g9519 is not orderable. The covers are built as an asm from the vendor, use ref 10 FRU p/n11h3758

## SAS KEYWORDS:

701X	7012	POWER BUTTON	PLANAR
BUTTON	LED	ERRORS	DOCUMENTATION
701X	DESKTOP	3XX	SA232624
D/T7012			

## 1.2.37 7012/39H MEMORY SIMM COMPATABILITY

Record number: H137357

Device: D/T7012  
Model: M39H  
Tip key: 021  
Date created: 097/04/11  
Date last altered: A97/12/08

The S4.5 and the S4.6 memory base cards will support 2 different FRU number simms that are equivalent.

4mb simm: p/n70f9973 = p/n12h1677  
8mb simm: p/n70f9976 = p/n12h1678  
16mb simm: p/n43g1796 = p/n12h1679  
32mb simm: p/n39h8312 = p/n12h1680

The problem of LED888/103 145/912 on boot at minimum config with the memory card plugged in and the 8 simms installed on the CPU of the 39H, will occur if the simm FRUs p/n12h16XX numbers are installed on the CPU.

NOTE: The base card and CPU must both be fully populated with the same size simms.

The FRU p/n12h16XX simms were developed with a resistor on the simm for the older S4.5 noise problem. They were not approved for installation on CPUs that support simm modules.

Times this might occur is model upgrades and or EC/MES activity.

## SAS KEYWORDS:

7012	701X	RISC6000	RISC
SRN145/912	39H	390H	P/N52G4801
RS6000	MEMORY		

1.3 Chapter 3. Parts Information Tips

Subtopics

1.3.1 CABLE P/N TO ATTACH 6091 TO 7010 X-STATION

1.3.2 GROUND STRAP PART NUMBER

1.3.3 5 PACK (8MM TAPES) NO LONGER AVAILABLE THROUGH PARTS SYSTEM

## 1.3.1 CABLE P/N TO ATTACH 6091 TO 7010 X-STATION

Record number: H037506

Device: D/T701X  
 Model: M  
 Part number: P/N58F2901  
 Tip key: 005  
 Date created: 090/04/09  
 Date last altered: A93/04/06

THE CABLE REQUIRED TO ATTACH THE 6091 GRAPHICS DISPLAY, MODEL 19 TO THE 7010 X-STATION IS P/N58F2901.

THIS CABLE HAS FIVE CONNECTORS THAT ATTACH TO THE REAR OF THE 6091 M19 (RED, GREEN, BLUE, BLACK, AND WHITE).

THIS INFORMATION IS AVAILABLE IN THE SERVICE DOCUMENTATION FOR THE 7010 X-STATION. THE FORM NUMBER FOR THE SERVICE GUIDE IS: SA23 - 2657 - 00.

MACHINES AFFECTED: 7010, 7012, 7013, 7015, 7016.

NOTE: THE CABLE P/N58F2903 IS A THREE CONNECTOR RGB CABLE AND CANNOT BE USED ON THE 7010 X-STATION AT THIS TIME.

## SAS KEYWORDS:

701X	D/T7010	D/T7012	D/T7013
D/T7015	D/T7016	701XPART	7010PART
7012PART	7013PART	7015PART	7016PART
RS6000	RS/6000	D/T6091	

7012 RETAIN TIPS  
GROUND STRAP PART NUMBER

1.3.2 GROUND STRAP PART NUMBER

Record number: H096360

Device: D/T7012  
Model: M  
Part number: P/N40F9958  
Tip key: 006  
Date created: 092/01/28  
Date last altered: A92/02/18

THE GROUND STRAP FOR THE D/T7012 KEYLOCK ASSEMBLY (EARLY MACHINES) HAS BEEN OBSOLETE WITH NO COUNTER PART NUMBER FOR THE NEW COVER DESIGN. THIS STRAP, P/N40F9958, IS NOT USED IN THE NEW COVER DESIGN.

IF THE STRAP IS NEEDED, THE CE MUST ORDER ANOTHER COVER SET AS FOLLOWS:

P/N81F9025 - FRONT BEZEL (QTY 1)  
P/N81F9039 - CARD GUIDE (QTY 1)  
P/N00G2981 - FAN ASSEMBLY (QTY 1)  
P/N00G2259 - FAN FOAM (QTY 1)  
P/N00G2258 - FRONT FAN DUCT (QTY 1)  
P/N81F7977 - SHOCK MOUNTS (QTY 1, 4 IN A PACKAGE)

THERE WILL ONLY BE A FEW CASES WHEN THE GROUND STRAP IS NEEDED, THEREFORE, AN ECA WILL NOT BE AVAILABLE. BRANCH OFFICE COST OF THESE FRU'S ARE MINIMAL.

SAS KEYWORDS:

701X	7012	7012PART	701XMISC
7012MISC	RS6000	RS/6000	D/T701X

## 1.3.3 5 PACK (8MM TAPES) NO LONGER AVAILABLE THROUGH PARTS SYSTEM

Record number: H037577

Device: D/T701X  
 Model: M  
 Part number: P/N21F8595  
 Tip key: 117  
 Date created: 092/05/21  
 Date last altered: A92/05/21

THE PACKAGE OF FIVE 8MM BLANK TAPES (P/N 21F8595) HAS BEEN REMOVED FROM THE MECHANICSBURG PART SYSTEM. THIS SUPPLY ITEM CAN BE ORDERED FROM IBM'S AUTHORIZED DISTRIBUTORS OR BY PART NUMBER FROM IBM DIRECT RESPONSE MARKETING AT 1-800-426-2468.

CE'S NEEDING A BLANK TAPE FOR TEST PURPOSES ONLY SHOULD ORDER  
 P/N 21F8575.

## SAS KEYWORDS:

RS6000	RS/6000	D/T7012	D/T7013
D/T7011	D/T7015	D/T7016	D/T7018
8MM	MEDIA	D/T7208	7011
7012	7013	7015	7016
7018	RISC	RISC/6000	701XTAPE
701XPART	701XMISC		

1.4 Chapter 4. Symptom/Fix Tips

Subtopics

- 1.4.1 CHECKSTOP ERRORS WITH S4.5 BASE MEMORY CARDS
- 1.4.2 D/T7012 BASE WILL NOT ATTACH TO THE SIDE MOUNTING HOLES
- 1.4.3 DIFFICULTY INSERTING IBM AND 3M LOGO 1/4 " TAPE CARTRIDGES.
- 1.4.4 FLASHING 888 DURING NETWORK BOOT ON 7012/7030 SYSTEMS
- 1.4.5 LED 201 HALT CAUSED BY AIX SW ON RS/6000
- 1.4.6 LED888/103 123/711 AFTER DISCONNECTING BATTERY
- 1.4.7 LOSS OF CONNECTIVITY THROUGH ETHERNET TP RISER CARD 00G1276
- 1.4.8 MALL, RECEIVE TIMEOUT FROM NEW RS6000 ( D/T701\* )
- 1.4.9 SYSDMA (OR DMA\_ERR) ENTRIES WITH GT3I IN 7012/7030 MACHINES
- 1.4.10 UNABLE TO READ/RESTORE 8MM TAPES

## CHECKSTOP ERRORS WITH S4.5 BASE MEMORY CARDS

## 1.4.1 CHECKSTOP ERRORS WITH S4.5 BASE MEMORY CARDS

Record number: H123163

Device: D/T701X  
 Model: M  
 Tip key:  
 Date created: 094/03/03  
 Date last altered: A97/04/15

**SYMPTOM:**

MACHINES AFFECTED: D/T7012 MODELS 37x  
 D/T7013 MODELS 58x & 59x  
 D/T7015 MODELS 98x & 99x

**SYMPTOM:**

SYSTEM RE-IPLS INTERMITTENTLY. CHECKSTOP ERROR IS RECORDED IN SYSTEM ERROR LOG AT TIME OF RE-IPL.

**PROBLEM ISOLATION AIDS:**

IF CHECKSTOP ERRORS ARE IDENTIFIED ON THE ABOVE MACHINE TYPES & MODELS VERIFY THE SYSTEM MEMORY CONFIGURATION BY RUNNING THE COMMAND:

```
Lscfg -v | pg
```

CHECK THE EC LEVEL OF ANY 64MB S4.5 MEMORY CARDS INSTALLED.

IF THE EC LEVEL IS 33, THEN THE CHECKSTOP FILES IN AIX MUST BE ANALYZED BY CHICAGO SUPPORT BEFORE REPLACING ANY PARTS.

IF THE EC LEVEL IS < 21 ON A 58x, 98x, or 37x; OR < 33 ON A 59x or 99x SYSTEM, THEN THE CARD FRU PART NUMBER WILL NEED TO BE READ DIRECTLY FROM THE CARD (INCORRECT EC LEVEL INFORMATION COULD BE OBTAINED AT SOME AIX LEVELS). IF THE CARD IS FRU P/N65G1803, THEN THE CHECKSTOP FILES IN AIX MUST BE ANALYZED BY AUSTIN PRODUCT ENGINEERING BEFORE REPLACING ANY PARTS.

**FIX:**

REFER TO RETAIN TDR #H096637 FOR INSTRUCTIONS TO COPY CHECKSTOP FILES TO DISKETTE. CONTACT THE SUPPORT CENTER TO OPEN A PROBLEM RECORD.  
 CHICAGO SUPPORT WILL PROVIDE AN ACTION PLAN AFTER ANALYZING THE CHECKSTOP FILES.

## SAS KEYWORDS:

701X	7013	7015	RISC
701XHALT	7013HALT	7015HALT	RS6000
RISC/6000	4.5	590	58H
990	370	701358H	7012370
7013590	7015990	MEMORY	EC 33

## 1.4.2 D/T7012 BASE WILL NOT ATTACH TO THE SIDE MOUNTING HOLES

Record number: H066964

Device: D/T7012  
 Model: M  
 Tip key:  
 Date created: 090/06/11  
 Date last altered: A91/02/14

**SYMPTOM:**

THE BASE ON THE 7012 SYSTEM UNIT IS DESIGNED TO ATTACH TO EITHER THE BOTTOM OR SIDE MOUNTING HOLES. SOME EARLY PRODUCTION SYSTEM UNITS WERE MANUFACTURED WITH THE SIDE MOUNTING BRACKETS ALIGNED IMPROPERLY. THE BASE WILL NOT ATTACH TO THE SIDE MOUNTING HOLES ON THESE EARLY PRODUCTION SYSTEMS.

DO NOT USE LONGER SCREWS TO MOUNT THE BASE.

**PROBLEM ISOLATION AIDS:**

CHECK THAT THE THREADED MOUNTING BRACKETS ARE ALIGNED FLUSH AGAINST THE SIDE COVER. THERE SHOULD NOT BE ANY SPACE BETWEEN THE BRACKET AND SIDE COVER.

**FIX:**

USE ONE OF THE TOP COVER REAR MOUNTING SCREWS TO DRAW THE THREADED BRACKETS AGAINST THE SIDE COVER. USE THE FOLLOWING PROCEDURE:

1. REMOVE ONE OF THE TOP COVER KNURLED MOUNTING SCREWS
2. UNSCREW THE PLASTIC BUSHING THAT HOLDS THE TOP COVER SCREW IN PLACE
3. PLACE A WASHER AGAINST THE OUTSIDE OF THE SIDE COVER TO PREVENT COVER DAMAGE
4. INSERT THE SCREW THROUGH THE WASHER & SIDE COVER AND THREAD INTO THE MOUNTING BRACKET
5. TIGHTEN THE SCREW UNTIL THE BRACKET IS PULLED AGAINST THE SIDE COVER
6. FOLLOW STEPS 3 - 5 TO ALIGN THE SECOND MOUNTING BRACKET
7. REINSTALL THE BUSHING ON THE TOP COVER SCREW
8. REINSTALL THE SCREW AND BUSHING IN THE TOP COVER

THE BASE CAN NOW BE ATTACHED TO THE SIDE COVER.

THE ABOVE PROCEDURE WILL ALIGN THE BRACKETS WITHOUT HAVING TO REMOVE ANY INTERNAL COMPONENTS.

**SAS KEYWORDS:**

D/T701X	D/T7012	RS6000	RS/6000
701XMISC	7012MISC	701X	7012

## DIFFICULTY INSERTING IBM AND 3M LOGO 1/4 " TAPE CARTRIDGES.

## 1.4.3 DIFFICULTY INSERTING IBM AND 3M LOGO 1/4 " TAPE CARTRIDGES.

Record number: H095354

Device: D/T7207  
 Model: M  
 Tip key:  
 Date created: 091/06/14  
 Date last altered: A91/09/13

**SYMPTOM:** THERE IS A SLIGHT MANUFACTURING DEFECT IN SOME IBM LOGO AND 3M BRAND TAPE CARTRIDGES, CAUSING THE TAPE DRIVE DOOR TO BE HARD TO CLOSE AFTER INSERTING THE TAPE CARTRIDGE. THE CAUSE OF THIS PROBLEM IS A SHARP EDGE ON THE ALUMINUM BASE PLATE, LOCATED AT THE CORNER OF THE TAPE CARTRIDGE NEAR THE (SAFE) PLUG. THE SHARP EDGE THAT NEEDS TO BE REMOVED IS A SMALL 5/16TH INCH WIDE AREA AT THE CORNER OF THE PLATE.

**PROBLEM ISOLATION AIDS:**

THIS PROBLEM WILL ONLY BE FOUND ON CARTRIDGES WITH THE FOLLOWING DATE CODES:

1/4" DC 6150 CARTRIDGES MANUFACTURED 10/26/90 THROUGH 01/30/91.  
 1/4" DC 6037 CARTRIDGES MANUFACTURED 07/19/90 THROUGH 01/30/91.

.  
 .  
 .  
 .  
 .

DATE CODES ON CARTRIDES CAN BE READ AS FOLLOWS:

XX	XX	XX	XX	XX	
					YEAR
					DAY
					MONTH
					MINUTE
					HOUR

**FIX:**

THE BURR CAN BE ELIMINATED BY LIGHTLY RUBBING THE SHARP EDGE WITH A METAL OBJECT ( A COIN WILL WORK FINE ). WIPE OFF METAL DUST BEFORE INSERTING THE CARTRIDGE.

## SAS KEYWORDS:

701X	7207	7207MISC	7207SAS
7012	7013	7012MISC	7013MISC
7015	7016	7015MISC	7016MISC
7016TAPE	7015TAPE	7012TAPE	7013TAPE
701XTAPE	D/T7207	D/T7012	D/T7013
D/T7015	D/T7016	RS6000	RS/6000
7018	7018MISC	7018TAPE	D/T7018

## 1.4.4 FLASHING 888 DURING NETWORK BOOT ON 7012/7030 SYSTEMS

Record number: H002043

Device: D/T7012  
 Model: M  
 Tip key:  
 Date created: 096/05/09  
 Date last altered: A97/09/02

**SYMPTOM:**

A flashing 888-103-202-226 -or- 888-103-202-231 may occur during a network boot from an ethernet adapter. The ethernet adapter can be either the integrated Ethernet or Microchannel ethernet adapter. This error will only occur during the IPLROS bootup phase (ie when the 3-digit LED display is rolling through the 2xx-series numbers) and the ethernet network boot option is selected.

**PROBLEM ISOLATION AIDS:****WORKAROUND:**

Try the remote boot again. If possible, reduce the network traffic or boot during times of low traffic on the network. If particular, if more than one machine is attempting network boot, scale it to only this machine. The more machines attempting to network boot, the greater the chance of hitting this problem.

**FIX:**

This problem is only on a certain vintage of CPUs. The part numbers (located on the barcode label on the CPU card) affected are listed below:

380/3AT CPUs: 40H2707  
 390/3BT CPUs: 40H2695, 40H2702

The permanent fix requires a new IPLROS module. The offending IPLROS level is "IPLVER1.2 LVL1.05". You can get this information by typing in the command "lscfg -vl sysplanar0" and looking at the "ROS Level and ID" field. This change has already been incorporated into manufacturing and reflected in FRU numbers 40H6723 (380/3AT) and 40H6717 (390/3BT). If you need a corrected IPLROS module, have Chicago contact the 7012/7030 Product Engineer in Austin.

**SAS KEYWORDS:**

7012	7030	380/3AT	390/3BT
380	7012/380	7012MOD380	7012MODEL380
390	7012/390	7012MOD390	7012MODEL390
7030/3AT	7030MOD3AT	7030MODEL3AT	7030/3BT
7030MOD3BT	7030MODEL3BT	3AT	3BT
LED888/103	IPLROS	ROS	PLANAR
SYSPLANAR	LED888	SRN202/226	SRN202/231
202/231	888/103 202/226	888/103 202/231	202/226

## 1.4.5 LED 201 HALT CAUSED BY AIX SW ON RS/6000

Record number: H064698

Device: D/T701X  
 Model: M  
 Tip key:  
 Date created: 090/09/11  
 Date last altered: A92/08/03

**SYMPTOM:**

SYSTEM HALTS WITH A 201 IN THE THREE DIGIT LED DISPLAY DURING DISK IPL FROM EITHER THE NORMAL OR SERVICE POSITION. IPL FROM DIAGNOSTIC DISKETTES COMPLETES SUCCESSFULLY.

MACHINES AFFECTED: 7012, 7013, 7015, 7016

**PROBLEM ISOLATION AIDS:**

VERIFY THE SEQUENCE OF LED'S DURING IPL. IF THE LED'S GO PAST 299 AND THEN HALT WITH A 201, SUSPECT SW. THIS SYMPTOM OCCURS ON SYSTEMS THAT HAVE RECENTLY INSTALLED AIX VERSION 3, REL 1. THE AIX BASE OPERATING SYSTEM CODE AND LICENSED PROGRAM PRODUCTS APPEAR TO INSTALL SUCCESSFULLY. HOWEVER, THE SYMPTOM USUALLY OCCURS AT THE FIRST IPL AFTER THE NEW VERSION OF AIX HAS BEEN INSTALLED.

**FIX:**

DIRECT THE USER TO CONTACT AIX SOFTWARE DEFECT SUPPORT AT 1 - 800-237 - 5511 FOR ASSISTANCE. A WORKAROUND IS AVAILABLE AND A FIX WILL BE INCLUDED IN A FUTURE RELEASE OF AIX.

IF DISKETTE DIAGNOSTICS LOAD AND RUN SUCCESSFULLY DO NOT REPLACE ANY HARDWARE FOR THIS PROBLEM.

**SAS KEYWORDS:**

RS6000	701X	7012	7013
7015	7016	D/T7012	D/T7013
D/T7015	D/T7016	701XIPL	7012IPL
7013IPL	7015IPL	7016IPL	701XLED
7012LED	7013LED	7015LED	7016LED
701XMISC	7012MISC	7013MISC	7015MISC
7016MISC	LED201		

## 1.4.6 LED888/103 123/711 AFTER DISCONNECTING BATTERY

Record number: H097770

Device: D/T7012  
 Model: M  
 Tip key:  
 Date created: 092/05/18  
 Date last altered: A97/04/15

**SYMPTOM:**

MACHINE AFFECTED: 7012 Models 340 and 350, only.

**SYMPTOM:**

Flashing LED888 may appear during the first power on cycle after disconnecting the battery. This occurs within 30 seconds after power on during BIST. The last LED prior to the flashing LED888 is LED153. The LED sequence obtained from pushing the reset button is:

LED888/103 123/711 ccc/104 003/c10

This problem is intermittent.

**PROBLEM ISOLATION AIDS:**

This failure is intermittent. It may, or may not, occur during the first IPL. If it does occur, power off and on again. The error should not reoccur unless the battery is disconnected. If it does not occur on the first power on cycle, the error will not occur unless the battery is disconnected again.

**FIX:**

An EC is being processed to update the OCS to level 7.2 which contains the fix for both 340 and 350 units. The OCS is located on the CPU card.

**SAS KEYWORDS:**

701X	7012	701XLED	7012LED
701XPOST	7012POST	RS6000	RS/6000
701XPWR	7012PWR	701XLOGICPROC	7012LOGICPROC

## 1.4.7 LOSS OF CONNECTIVITY THROUGH ETHERNET TP RISER CARD 00G1276

Record number: H002545

Device: D/T7012  
Model: M  
Tip key:  
Date created: 097/03/06  
Date last altered: A98/03/12

**SYMPTOM:**

A LOSS OF CONNECTIVITY WITH THE ETHERNET LAN PROBLEM MAY BE INTERMITTANT.

**PROBLEM ISOLATION AIDS:** A problem has arisen with Ethernet Riser Card , Twisted Pair ( UTP ) P/N 32G2000, EC#C74129, FRU#00G1276. The RJ45, female connector on the adapter ( IBM P/N 02G7328 ) , by AMP ( P/N 555162-1 ) , Location J2 , may have the recessed contacts inside a connector NOT providing the parallel contact surface to the inserted 8-pin RJ45 modular male plug. In some cases, each individual contact may be projecting inward at a different angle, and also NOT at a sufficient angle to provide good, reliable contact. Typically, the outer contacts ( pins 1,2 7,8 ) seem to be "ramping up" at the higher angle than the middle pins.

The problem has been reported as intermittent and prone to show up with the box sitting in the vertical position. In this position , the weight of the attached cable may be pulling a male plug away from already "too low" female connectors.

**FIX:**

The stock has been purged. If a system appears to have the "connectivity" problem in the field, one should be advised to attempt to lift the contact and to order the above FRU as a replacement.

## SAS KEYWORDS:

7012                      7030                      ETHERNET                      RISER  
TWISTED PAIR

## 1.4.8 MALL, RECEIVE TIMEOUT FROM NEW RS6000 ( D/T701\* )

Record number: H124151

Device: D/T3745  
 Model: MALL  
 Tip key:  
 Date created: 094/05/26  
 Date last altered: A94/06/02

**SYMPTOM:** Ce had just installed a RISC6000 system to a 3745 via a direct attached v.35 LIC3. The line would not activate. This problem could arise when attaching a RISC 6000 to a d/t3720 d/t3721 , d/t3746 , d/t3725 , d/t3726 and d/t3705 .

---

3745 3746 3720 3721 3725 3726 3705 7012 risc6000 6000 d/t7012  
 rs/6000 rs6000 d/t701x 701x d/t7013 7013 d/t7015 7015 d/t7016  
 7016 d/t7018 7018 d/t7011 7011

**PROBLEM ISOLATION AIDS:** No BERs were logged. All TSS diags and wrap tests ran without errors. We compared the NCP gen parameters that we saw in the LID with the setup screens on the d/t 7012 . All seemed to be correct. Next we ran a SIT trace on the failing line from the support center. We saw " RECEIVE TIMEOUT , ( no response from SDLC ADDRESS " 21 " ). At that point we knew that problem was either a broken or incorrectly configured RISC6000 .

**FIX:** The configuration setup screens on the D/T7012 use DECIMAL values instead of HEX. They had entered " 21 " into the setup screen thinking that it was SDLC station address HEX 21. When they changed it to " 33 " and reactivated the line it came right up !

## SAS KEYWORDS:

3745CNFG	3745CS	3745CSSIT	3745FESL
3745LSSERR	3745TSS	3745INST	3745LIC
3745LIC1	3745LIC3	3745MODALL	3720CNFG
3720CS	3720CSSIT	3720FESL	3720LSSERR
3720TSS	3720INST	3720LIC	3720LIC1
3720LIC3	3746CNFG	3746CS	3746CSSIT
3746FESL	3746LSSERR	3746TSS	3746INST
3746LIC	3746LIC1	3746LIC3	3721CNFG
3721CS	3721CSSIT	3721FESL	3721LSSERR
3721TSS	3721INST	3721LIC1	3721LIC3
3725CNFG	3725CS	3725CSSIT	3725FESL
3725LSSERR	3725TSS	3725INST	3725LIC
3725LIC1	3725LIC3	3725MODALL	3726CNFG
3726CS	3726CSSIT	3726FESL	3726LSSERR
3726TSS	3726INST	3726LIC	3726LIC1
3726LIC3	3705CNFG	3705CS	3705CSSIT
3705FESL	3705LSSERR	3705TSS	3705INST
3705LIC	37051D	1D	

## SYSDMA (OR DMA\_ERR) ENTRIES WITH GT3I IN 7012/7030 MACHINES

## 1.4.9 SYSDMA (OR DMA\_ERR) ENTRIES WITH GT3I IN 7012/7030 MACHINES

Record number: H13596

Device: D/T7012  
 Model: M  
 Tip key:  
 Date created: 095/08/24  
 Date last altered: A95/11/15

**SYMPTOM:**

Error log will report SYSDMA (UNDETERMINED ERROR) with a GT3i (LEGA2) graphics adapter populated in slot 4 and Microchannel slots 1 through 3 empty. It doesn't happen on every machine and may range from zero to multiple error entries per day dependent on the amount of GT3i activity. This will not affect overall system performance. and in most cases will go unnoticed by the customer other than the error entries.

A problem has also been reported with a GXT150M (Neptune) adapter in slot 4 and is a potential for any busy master adapters in this slot. The probability, however, is minimal that any adapter will see this problem.

**PROBLEM ISOLATION AIDS:**

Move the microchannel adapter in slot 4 to a lower slot number or add more microchannel adapters to the system (thus creating a heavier load on the microchannel bus). If the failing symptoms go away, then it is symptomatic of this problem.

**FIX:**

Workaround:  
 Move the microchannel adapter from slot 4 to a lower slot (i.e. slot 1), which should fix the problem. No replacement of the I/O planar is necessary. Mfg. has advised to restrict th GT3i adapter in slot 1 when no other microchannel adapter slots are populated.

**Permanent Fix:**

ECD74660 is forthcoming which includes a fix to this problem (-CMD signal reflection problem). There will be a new FRU number p/n40H6690 released as part of this EC for this I/O planar and will be installed on subsequent new build machines. Expected availability of the new FRU is January 1996.

**SAS KEYWORDS:**

7030	7012	7012/390	7012-390
7012/380	7012-380	7030/3AT	7030-3AT
7030/3BT	7030-3BT	RS6000	RISC
GT3I	DMA_ERR	DMA ERROR	SYSDMA
GRAPHICS			

## 1.4.10 UNABLE TO READ/RESTORE 8MM TAPES

Record number: H066069

Device: D/T701X  
 Model: M  
 Tip key:  
 Date created: 090/11/14  
 Date last altered: A95/03/13

**SYMPTOM:**

1. USER IS UNABLE TO READ 8MM TAPES CREATED ON ANOTHER SYSTEM OR ON ANOTHER 7208 TAPE DRIVE.
2. USER IS UNABLE TO RESTORE 8MM TAPES THAT WERE CREATED OR BACKED UP PRIOR TO A RELOAD OF AIX OPERATING SYSTEM CODE.

MACHINES AFFECTED: D/T7012, D/T7013, D/T7015, D/T7016, D/T7208

**PROBLEM ISOLATION AIDS:** NONE**FIX:**

HAVE THE USER CHECK THE "BLOCK SIZE" VALUE FOR THE 8MM TAPE DRIVE IN AIX. THE "BLOCK SIZE" MUST BE SET TO THE SAME VALUE WHEN WRITING AND READING TAPES.

THE DEFAULT "BLOCK SIZE" VALUE SET BY AIX IS EITHER 512 OR 1024.

THE PARAMETERS FOR THE 2.3 GB 8MM TAPE DRIVE MAY BE DISPLAYED/CHANGED BY ENTERING 'SMIT' FROM THE AIX PROMPT.

```
SELECT 'DEVICES'
SELECT 'TAPE DRIVE'
SELECT 'CHANGE/SHOW CHARACTERISTICS OF A TAPE DRIVE'
SELECT '2.3GB 8MM TAPE DRIVE'
```

IF THE "BLOCK SIZE" VALUE IS SET TO 512, CHANGE TO 1024.  
 IF THE "BLOCK SIZE" VALUE IS SET TO 1024, CHANGE TO 512.  
 THEN TRY THE TAPE READ/RESTORE OPERATION AGAIN.

**SAS KEYWORDS:**

701X	7012	7013	7015
7016	7208	701XMISC	7012MISC
7013MISC	7015MISC	7016MISC	7208MISC
RS6000	701XTAPE	7012TAPE	7013TAPE
7015TAPE	7016TAPE		

**L A S T P A G E**