

# HiPPI Protocol Support Services, Version 4.5.0 Release Notes

## HiPPI Protocol Support Services, Version 4.5.0 Release Notes

**Memorandum to: Licensees of HiPPI Protocol Support Services, Version 4.5.0**

**Subject: HiPPI Protocol Support Services, Version 4.5.0**

**Release Notes Version: 1.0**

Enclosed is information about HiPPI Protocol Support Services, Version 4.5.0. **Read this information before installing or mounting HiPPI Protocol Support Services, Version 4.5.0.**

Copyright International Business Machines Corporation 1997, 2001. All rights reserved.

---

### **Table of Contents**

**[HiPPI Protocol Support Services, Version 4.5.0 Release Notes](#)**

- [Trademarks](#)
- 

## HiPPI Protocol Support Services, Version 4.5.0 Release Notes

The following versions of the HiPPI LPP 5765-E40 are currently available:

- HiPPI Protocol Support Services, Version 4.3.2 is an enhancement to early releases that incorporates PTF's (code changes and fixes) into a formal release. The HiPPI protocols supported in this level include IPI-3, Framing Protocol, and NDA.
- HiPPI Protocol Support Services, Version 4.5.0 contains enhancements for use with IBM eServer pSeries 690 servers and special features for AIX 5.1. The HiPPI protocols supported in this level are IPI-3 and Framing Protocol. It does not support NDA.

If migrating from HiPPI 4.3.x to HiPPI 4.5.0, `hippi.nda` must be deinstalled. Any HiPPI disk array devices should be removed first. This can be done manually before the migration or it will be done as part of the migration.

This release contains the latest version of the adapter resident flash images. To determine if the latest flash image is installed on the HiPPI adapter, run the following script:

```
/usr/bin/hippi/flash/flash_check hippi0 (assuming hippi0)
```

**Note:** During the update, *yes* must be spelled out at the prompt.

If you have more than one HiPPI adapter, run the above script for each adapter. If the firmware is not current, instructions on how to update the adapter will be provided as output of the `/usr/bin/hippi/flash/flash_check` command.

---

## Trademarks

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both:

- AIX
- e (logo)
- IBM
- pSeries

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Sun Microsystems, Inc. in the United States, other countries, or both.